

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/AIG24120022/AUA3Q2

Date: 16/04/2025

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100311465

Claimant Vehicle No : EG5566E Insured Vehicle No : SKG2834E

Date of Loss: 30/11/2024 Nature of Claim: TP Claim No: 7231910032SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: EG5566E

Make & Model: BMW X3 M40I, 3.0 (A) Engine No: 14795387B58B30A

Reg. Date: 02/11/2018 (Man. Year: 2018) Chassis No: WBATS32040LE86946

Colour: Blue Odometer: 72402 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/35 R21 Rear Tyre Size: 295/35 R21

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                             | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------------------------|------------|------------|------------|--------|
| Parts                                      | 68,023.35  | 37,381.46  | 30,641.89  | 45.05  |
| Miscellaneous Items                        | 0.00       | 0.00       | 0.00       |        |
| Labour                                     | 11,300.00  | 3,480.00   | 7,820.00   | 69.20  |
| Paintwork Labour                           | 0.00       | 0.00       | 0.00       |        |
| Towing                                     | 0.00       | 0.00       | 0.00       |        |
| Calculated Gross Total (S\$)               | 79,323.35  | 40,861.46  | 38,461.89  | 48.49  |
| Approved Total (Overridden) (S\$)          |            | 32,650.00  |            |        |
| (S\$)                                      | 79,323.35  | 32,650.00  | 46,673.35  | 58.84  |
| + GST 9.00/9.00% (S\$)                     | 7,139.10   | 2,938.50   | 4,200.60   | 58.84  |
| Nett Amount (S\$)                          | 86,462.45  | 35,588.50  | 50,873.95  | 58.84  |
| + Loss of Use (14.0 x S\$100.00/day) (S\$) |            | 1,400.00   |            |        |
| + Doc/Search Fee (S\$)                     |            | 27.25      |            |        |
| + Other Costs (S\$)                        |            | 140.00     |            |        |
| Nett Liability (S\$)                       |            | 37,155.75  |            |        |
| Global Sum Settlement (S\$)                |            | 37,150.00  |            |        |

INSPECTION

Date of Assignment: 03/12/2024

Date Inspected: 03/12/2024 Inspected At: JL Perfect Autowork Pte Ltd (HQ)  
8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit  
Singapore 415875

Estimated Period of Repair: 12.0 days

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                                    | Condition            | Repairer's   | Amount        |
|-----|-----|----------|------------------------------------------------|----------------------|--------------|---------------|
| 1   | 1   |          | *FRONT BUMPER                                  | Deformed             | 2,485.50 FL  | *1,854.00 FL  |
| 2   | 1   |          | *FRONT BUMPER TOWING COVER                     | Not Necessary        | 78.45 FL     | *- FL         |
| 3   | 1   |          | *FRONT BUMPER NUMBER PLATE GARNISH             | Deformed             | 120.87 FL    | *120.87 FL    |
| 4   | 2   |          | *FRONT BUMPER CORNER INNER SUPPORT             | Not Necessary        | 247.70 FL    | *- FL         |
| 5   | 1   |          | *FRONT BUMPER CAMERA                           | Not Necessary        | 2,138.20 FL  | *- FL         |
| 6   | 2   |          | *FRONT BUMPER SIDE BRACKET                     | Not Necessary        | 135.10 FL    | *- FL         |
| 7   | 2   |          | *FRONT BUMPER FOG LIGHT                        | Cracked              | 1,543.60 FL  | *1,543.60 FL  |
| 8   | 2   |          | *FRONT BUMPER DAY FOG LIGHT COVER GARNISH      | Cracked              | 197.00 FL    | *197.00 FL    |
| 9   | 2   |          | *FRONT BUMPER FOG LIGHT CHROME                 | Not Necessary        | 231.70 FL    | *- FL         |
| 10  | 2   |          | *FRONT BUMPER SENSOR                           | Damaged (1 PCS ONLY) | 1,539.10 FL  | *350.00 FL    |
| 11  | 1   |          | *FRONT BUMPER SENSOR HOLDER<br>(6 PCS)         | Necessary            | 429.00 FL    | *100.00 FL    |
| 12  | 1   |          | *FRONT BUMPER CENTER GRILLE FRAME              | Cut                  | 375.80 FL    | *375.80 FL    |
| 13  | 1   |          | *FRONT BUMPER CENTER BOTTOM GARNISH            | Not Necessary        | 315.40 FL    | *- FL         |
| 14  | 2   |          | *FRONT BUMPER SIDE BOTTOM GARNISH              | Not Necessary        | 122.80 FL    | *- FL         |
| 15  | 1   |          | *FRONT BUMPER SIDE AIR DUCT RH                 | Not Necessary        | 65.85 FL     | *- FL         |
| 16  | 1   |          | *FRONT BUMPER SPONGE                           | Cracked              | 100.85 FL    | *100.85 FL    |
| 17  | 2   |          | *FRONT BUMPER CENTER BRACKET                   | Not Necessary        | 706.30 FL    | *- FL         |
| 18  | 1   |          | *FRONT BUMPER REINFORCEMENT                    | Dented               | 1,325.50 FL  | *980.00 FL    |
| 19  | 1   |          | *FRONT BUMPER LOWER BEAM                       | Bent                 | 822.00 FL    | *495.00 FL    |
| 20  | 2   |          | *FRONT GRILLE C/W CHROME                       | Cracked              | 1,108.00 FL  | *1,108.00 FL  |
| 21  | 1   |          | *FRONT LOWER AIR GUARD                         | Cracked              | 319.40 FL    | *319.40 FL    |
| 22  | 1   |          | *FRONT LOWER GRILLE                            | Cracked              | 302.45 FL    | *302.45 FL    |
| 23  | 2   |          | *HEADLAMP (LED)                                | Cracked              | 13,619.40 FL | *13,619.40 FL |
| 24  | 2   |          | *HEADLAMP LOWER BRACKET                        | Not Necessary        | 549.40 FL    | *- FL         |
| 25  | 1   |          | *HORN                                          | Not Necessary        | 186.30 FL    | *- FL         |
| 26  | 1   |          | *FRONT RADIATOR                                | Not Necessary        | 981.60 FL    | *- FL         |
| 27  | 2   |          | *FRONT RADIATOR MOUNTING                       | Not Necessary        | 241.70 FL    | *- FL         |
| 28  | 1   |          | *FRONT RADIATOR AIR GUARD                      | Not Necessary        | 356.75 FL    | *- FL         |
| 29  | 1   |          | *FRONT AIRCON CONDENSER                        | Not Necessary        | 847.98 FL    | *- FL         |
| 30  | 1   |          | *FRONT AIR DUCT                                | Not Necessary        | 356.75 FL    | *- FL         |
| 31  | 1   |          | *FRONT FENDER ARCED GARNISH RH (INNER)         | Not Necessary        | 238.60 FL    | *- FL         |
| 32  | 1   |          | *FRONT FENDER ARCED GARNISH RH (OUTER)         | Not Necessary        | 345.70 FL    | *- FL         |
| 33  | 1   |          | *FRONT FENDER COWLING RH                       | Not Necessary        | 164.55 FL    | *- FL         |
| 34  | 1   |          | *TAILGATE                                      | Dented               | 2,465.65 FL  | *2,465.65 FL  |
| 35  | 1   |          | *TAILGATE LAMP                                 | O/S Cut              | 1,273.40 FL  | *636.70 FL    |
| 36  | 1   |          | *TAILGATE LOGO                                 | Necessary            | 120.15 FL    | *120.15 FL    |
| 37  | 1   |          | *TAILGATE EMBLEM X3                            | Necessary            | 90.50 FL     | *90.50 FL     |
| 38  | 1   |          | *TAILGATE EMBLEM M40I                          | Necessary            | 78.90 FL     | *78.90 FL     |
| 39  | 1   |          | *TAILGATE INNER TRIM                           | Cracked              | 532.85 FL    | *532.85 FL    |
| 40  | 1   |          | *TAILGATE LOCK CONTROL MODULE SPONGE PROTECTOR | Not Necessary        | 742.20 FL    | *- FL         |
| 41  | 1   |          | *TAILGATE LOCK CONTROL MODULE                  | Cracked              | 371.80 FL    | *371.80 FL    |
| 42  | 1   |          | *TAILGATE WINDSCREEN MOULDING C/W WINDSCREEN   | Necessary            | 1,149.85 FL  | *210.00 FL    |
| 43  | 1   |          | *TAILGATE DETECTOR                             | Not Necessary        | 120.95 FL    | *- FL         |
| 44  | 1   |          | *TAILGATE WEATHERSTRIP                         | Cut                  | 185.85 FL    | *185.85 FL    |
| 45  | 1   |          | *REVERSE CAMERA                                | Not Necessary        | 990.58 FL    | *- FL         |
| 46  | 1   |          | *REAR FOOT SENSOR MODULE                       | Cracked              | 550.85 FL    | *410.00 FL    |
| 47  | 2   |          | *REAR FOOT SENSOR (UPPER AND BOTTOM)           | Not Necessary        | 141.00 FL    | *- FL         |
| 48  | 1   |          | *REAR FOOT SENSOR HOLDER                       | Cracked              | 143.20 FL    | *143.20 FL    |
| 49  | 1   |          | *REAR BUMPER                                   | Distorted            | 1,838.56 FL  | *1,740.00 FL  |
| 50  | 1   |          | *REAR BUMPER CENTER                            | Distorted            | 380.65 FL    | *380.65 FL    |
| 51  | 1   |          | *REAR BUMPER BOTTOM GARNISH                    | Deformed             | 137.60 FL    | *137.60 FL    |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                                     | Condition            | Repairer's  | Amount       |
|-----|-----|----------|-------------------------------------------------|----------------------|-------------|--------------|
| 52  | 1   |          | *REAR BUMPER REFLECTOR                          | O/S Cracked          | 121.80 FL   | *60.90 FL    |
| 53  | 1   |          | *REAR BUMPER TOW HOOK COVER                     | Missing              | 91.85 FL    | *91.85 FL    |
| 54  | 1   |          | *REAR BUMPER SENSOR<br>(4 PCS)                  | Damaged (2 PCS ONLY) | 1,078.20 FL | *539.10 FL   |
| 55  | 6   |          | *REAR BUMPER SENSOR HOLDER                      | Necessary            | 871.20 FL   | *150.00 FL   |
| 56  | 1   |          | *REAR BUMPER SENSOR WIRE HARNESS                | Snapped              | 850.15 FL   | *601.00 FL   |
| 57  | 1   |          | *REAR BUMPER BOTTOM SIDE GARNISH RH             | Not Necessary        | 146.30 FL   | *- FL        |
| 58  | 1   |          | *REAR BUMPER REINFORCEMENT                      | Dented               | 832.45 FL   | *832.45 FL   |
| 59  | 1   |          | *REAR BUMPER SIDE BRACKET (PLASTIC)             | O/S Deformed         | 399.20 FL   | *199.60 FL   |
| 60  | 1   |          | *REAR BUMPER CENTER BRACKET (PLASTIC)           | O/S Cracked          | 399.00 FL   | *199.50 FL   |
| 61  | 1   |          | *TAIL LAMP                                      | O/S Cracked          | 1,164.90 FL | *582.45 FL   |
| 62  | 1   |          | *TAIL LAMP PANEL LH                             | Not Necessary        | 640.80 FL   | *- FL        |
| 63  | 2   |          | *TAIL LAMP SIDE GARNISH                         | Not Necessary        | 161.80 FL   | *- FL        |
| 64  | 1   |          | *REAR BLIND SPORT SENSOR RH                     | Not Necessary        | 1,365.45 FL | *- FL        |
| 65  | 1   |          | *REAR FENDER RH                                 | Not Necessary        | 2,640.95 FL | *- FL        |
| 66  | 2   |          | *REAR FENDER INNER COWLING                      | Not Necessary        | 371.96 FL   | *- FL        |
| 67  | 2   |          | *REAR FENDER INNER TRIM                         | Not Necessary        | 879.60 FL   | *- FL        |
| 68  | 2   |          | *REAR WHEEL ARCED GARNISH                       | Not Necessary        | 490.40 FL   | *- FL        |
| 69  | 1   |          | *REAR END PANEL (INNER)                         | Repair               | 556.98 FL   | *- FL        |
| 70  | 1   |          | *REAR END PANEL (OUTER)                         | Dented               | 651.55 FL   | *651.55 FL   |
| 71  | 1   |          | *REAR END PANEL TOP GARNISH                     | Deformed             | 245.52 FL   | *245.52 FL   |
| 72  | 1   |          | *REAR FLOOR TOP BOARD                           | Not Necessary        | 830.70 FL   | *- FL        |
| 73  | 1   |          | *REAR SIDE TRAY RH                              | Not Necessary        | 121.50 FL   | *- FL        |
| 74  | 1   |          | *REAR ACTIVATED CHARCOAL FITTER                 | Cracked              | 289.85 FL   | *289.85 FL   |
| 75  | 1   |          | *REAR ACTIVATED CHARCOAL FITTER HOSE            | Not Necessary        | 123.55 FL   | *- FL        |
| 76  | 1   |          | *CENTER EXHAUST PIPE INSULATOR                  | Not Necessary        | 200.15 FL   | *- FL        |
| 77  | 4   |          | *CENTER EXHAUST MOUNTING                        | Not Necessary        | 112.60 FL   | *- FL        |
| 78  | 2   |          | *CENTER EXHAUST PIPE BRACKET                    | Not Necessary        | 157.56 FL   | *- FL        |
| 79  | 1   |          | *REAR EXHAUST PIPE WITH MUFFLER                 | Bent                 | 4,892.70 FL | *2,105.00 FL |
| 80  | 1   |          | *REAR EXHAUST MOUNTING<br>(4 PCS)               | Damaged              | 118.80 FL   | *29.70 FL    |
| 81  | 1   |          | *REAR EXHAUST PIPE BRACKET                      | Bent                 | 78.70 FL    | *78.70 FL    |
| 82  | 1   |          | *REAR EXHAUST MUFFLER INSULATOR (SIDE)          | Crumpled             | 116.85 FL   | *116.85 FL   |
| 83  | 1   |          | *REAR EXHAUST MUFFLER INSULATOR (CENTER)        | Crumpled             | 200.45 FL   | *200.45 FL   |
| 84  | 1   |          | *REAR CROSSMEMBER                               | Bent                 | 2,895.65 FL | *2,440.00 FL |
| 85  | 1   |          | *REAR LOWER ARM LH                              | Bent                 | 685.30 FL   | *480.00 FL   |
| 86  | 1   |          | *FRONT NUMBER PLATE                             | Cracked              | 80.00 FS    | *80.00 FS    |
| 87  | 1   |          | *SET FRONT BUMPER CLIP                          | Necessary            | 80.00 FS    | *30.00 FS    |
| 88  | 1   |          | *SET FRONT BUMPER FOGLAMP LOWER GARNISH CLIP RH | Not Necessary        | 50.00 FS    | *- FS        |
| 89  | 1   |          | *SET FRONT BUMPER CENTER GARNISH CLIP           | Not Necessary        | 50.00 FS    | *- FS        |
| 90  | 1   |          | *SET FRONT BUMPER CENTER BOTTOM GARNISH CLIP    | Necessary            | 60.00 FS    | *30.00 FS    |
| 91  | 1   |          | *SET FRONT BUMPER NUMBER PLATE GARNISH CLIP     | Necessary            | 60.00 FS    | *20.00 FS    |
| 92  | 1   |          | *SET FRONT LOWER GRILLE CLIP                    | Not Necessary        | 50.00 FS    | *- FS        |
| 93  | 1   |          | *SET FRONT AIR DUCT BASE GARNISH CLIP           | Not Necessary        | 50.00 FS    | *- FS        |
| 94  | 1   |          | *SET FRONT FENDER ARCED GARNISH CLIP RH         | Not Necessary        | 50.00 FS    | *- FS        |
| 95  | 1   |          | *SET FRONT FENDER COWLING CLIP RH               | Not Necessary        | 50.00 FS    | *- FS        |
| 96  | 1   |          | *REAR NUMBER PLATE                              | Bent                 | 80.00 FS    | *80.00 FS    |
| 97  | 1   |          | *SET REAR BUMPER CLIP                           | Necessary            | 80.00 FS    | *30.00 FS    |
| 98  | 1   |          | *SET REAR BUMPER BOTTOM GARNISH CLIP            | Not Necessary        | 80.00 FS    | *- FS        |
| 99  | 1   |          | *TAILGATE SEALANT                               | Not Necessary        | 150.00 FS   | *- FS        |
| 100 | 1   |          | *SET TAILGATE INNER TRIM CLIP                   | Necessary            | 50.00 FS    | *30.00 FS    |
| 101 | 1   |          | *TAILGATE WINDSCREEN GLASS SEALANT              | Necessary            | 100.00 FS   | *50.00 FS    |
| 102 | 1   |          | *TAILGATE WINDSCREEN GLASS INNER SEAL           | Necessary            | 80.00 FS    | *30.00 FS    |
| 103 | 1   |          | *TAILGATE WINDSCREEN GLASS SOLAR FILM           | Not Necessary        | 550.00 FS   | *- FS        |
| 104 | 1   |          | *SET TAIL LAMP CLIP                             | Not Necessary        | 30.00 FS    | *- FS        |
| 105 | 1   |          | *SET TAIL LAMP SIDE GARNISH CLIP                | Not Necessary        | 30.00 FS    | *- FS        |
| 106 | 1   |          | *SET REAR FENDER COWLING CLIPS                  | Not Necessary        | 80.00 FS    | *- FS        |
| 107 | 1   |          | *SET REAR FENDER INNER TRIM CLIPS               | Not Necessary        | 80.00 FS    | *- FS        |
| 108 | 1   |          | *REAR FENDER QUARTER GLASS SEALANT              | Not Necessary        | 80.00 FS    | *- FS        |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                              | Condition     | Repairer's | Amount    |
|-----|-----|----------|------------------------------------------|---------------|------------|-----------|
| 109 | 1   |          | *REAR FENDER QUARTER GLASS INNER SEAL    | Not Necessary | 80.00 FS   | *- FS     |
| 110 | 1   |          | *REAR FENDER QUARTER GLASS SOLAR FILM LH | Not Necessary | 350.00 FS  | *- FS     |
| 111 | 1   |          | *SET REAR WHEEL ARCED GARNISH CLIP       | Not Necessary | 50.00 FS   | *- FS     |
| 112 | 1   |          | *SET REAR END PANEL TOP GARNISH CLIPS    | Necessary     | 30.00 FS   | *20.00 FS |
| 113 | 1   |          | *REAR END PANEL INSULATION SEAL          | Necessary     | 150.00 FS  | *60.00 FS |
| 114 | 1   |          | *BRAKE OIL                               | Not Necessary | 50.00 FS   | *- FS     |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                         |                  |                  |
|---------------------------------------------------------|------------------|------------------|
| <b>Sub Total (S\$)</b>                                  | <b>71,458.26</b> | <b>39,324.69</b> |
| <b>- List Item Discount on L Items 5.00/5.00% (S\$)</b> | 3,434.91         | 1,943.23         |
| <b>Total Parts (S\$)</b>                                | <b>68,023.35</b> | <b>37,381.46</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                            | Lab.Type | Repairer's       | Amount          |
|---------------------------------|--------------------------------------------------------------------------------------------------------|----------|------------------|-----------------|
| <b>Labour Items</b>             |                                                                                                        |          |                  |                 |
| 1                               | PANEL BEATING ,REMOVING AND REPLACING PARTS (FRONT)                                                    | New      | 1,400.00         | 400.00          |
| 2                               | SPRAY PAINTING TO AFFECTED AREA (FRONT)                                                                | New      | 1,200.00         | 250.00          |
| 3                               | REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS (FRONT)                                        | New      | 120.00           | 0.00            |
| 4                               | REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST (FRONT)                                            | New      | 80.00            | 0.00            |
| 5                               | REFOCUS HEADLAMP BEAM (FRONT)                                                                          | New      | 80.00            | 0.00            |
| 6                               | REMOVE AND REFIX FRONT BUMPER SENSOR (FRONT)                                                           | New      | 80.00            | 50.00           |
| 7                               | REMOVE AND REFIX FRONT BUMPER CAMERA (FRONT)                                                           | New      | 80.00            | 50.00           |
| 8                               | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC (FRONT) | New      | 680.00           | 200.00          |
| 9                               | PANEL BEATING ,REMOVAL AND REPLACING PARTS (REAR)                                                      | New      | 2,000.00         | 1,000.00        |
| 10                              | TO SPRAY PAINT AFFECTED AREA (REAR)                                                                    | New      | 1,800.00         | 750.00          |
| 11                              | TUFF COAT (REAR)                                                                                       | New      | 250.00           | 60.00           |
| 12                              | WIRING CHECK (REAR)                                                                                    | New      | 80.00            | 30.00           |
| 13                              | CONDUCT WATER LEAKAGE TEST (REAR)                                                                      | New      | 180.00           | 0.00            |
| 14                              | REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR (REAR)                 | New      | 180.00           | 60.00           |
| 15                              | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING (REAR)                                            | New      | 80.00            | 50.00           |
| 16                              | REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING (REAR)                                            | New      | 80.00            | 50.00           |
| 17                              | REMOVE AND REFIX VIDEO RECORDER AND DISTANCE SETTING (REAR)                                            | New      | 80.00            | 50.00           |
| 18                              | REMOVE AND REFIX BLIND SPORT SENSOR AND REPROGRAMMING (REAR)                                           | New      | 1,200.00         | 0.00            |
| 19                              | FOUR WHEEL ALIGNMENT (REAR)                                                                            | New      | 120.00           | 80.00           |
| 20                              | CONDUCT WATER LEAKAGE TEST (REAR)                                                                      | New      | 80.00            | 0.00            |
| 21                              | REMOVE AND REFIX REAR SMART SENSOR AND RESET (REAR)                                                    | New      | 550.00           | 180.00          |
| 22                              | REMOVE AND REFIX TAILGATE WINDSCREEN (REAR)                                                            | New      | 120.00           | 120.00          |
| 23                              | RESET TAILGATE AUTO SYSTEM (REAR)                                                                      | New      | 350.00           | 0.00            |
| 24                              | REMOVE AND REFIX REAR EXHAUST PIPE (REAR)                                                              | New      | 180.00           | 100.00          |
| 25                              | REAR CHASSIS ALIGNMENT (REAR)                                                                          | New      | 250.00           | 0.00            |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                        |          | <b>11,300.00</b> | <b>3,480.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >