

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTIndia International Insurance Pte Ltd
6 Raffles Quay, #22-00
Singapore 048580**Our File No:** CS/III24120023/UVH3E2
Date: 30/12/2024**REFERENCE**

Insured/Claimant:	DL Repair & Aircon Services Pte Ltd	Policy No:	D22MCV0010320
Date of Loss:	01/12/2024	Nature of Claim:	OD
		Claim No:	MCV2024D0014339

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBL6599M		
Make & Model:	TOYOTA HIACE, 2.0 (A)	Engine No:	1TR2384062
Reg. Date:	28/12/2021 (Man. Year: 2021)	Chassis No:	TRH2000347863
Colour:	Silver	Odometer:	125019 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$77,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Grenlander 6 mm	Rear Left Side:	Grenlander 6 mm
Front Right Side:	Grenlander 6 mm	Rear Right Side:	Grenlander 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,767.53	12,095.56	2,671.97	18.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,900.00	2,440.00	2,460.00	50.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,667.53	14,535.56	5,131.97	26.09
- Excess (S\$)	600.00	600.00	0.00	0.00
Nett Amount (S\$)	19,067.53	13,935.56	5,131.97	26.91

INSPECTION

Date of Assignment:	03/12/2024		
Date Inspected:	04/12/2024	Inspected At:	Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120 Singapore 528838
Estimated Period of Repair:	7.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2024)
Parts:	213	TOYOTA HIACE 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL6599M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE COMP	Cracked	546.70 FL	*546.70 FL
2	1		*FRONT GRILLE INNER SUPPORT BASE	Not Necessary	488.20 FL	*- FL
3	6		*FRONT GRILLE CLIPS & STOPPER	Necessary	87.60 FL	*87.60 FL
4	1		*FRONT BUMPER	Distorted	942.00 FL	*942.00 FL
5	1		*FRONT BUMPER O/S SIDE BRACKET	Cracked	238.06 FL	*238.06 FL
6	10		*FRONT BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
7	1		*O/S HEAD LAMP COMP	Cracked	1,390.10 FL	*1,390.10 FL
8	1		*O/S HEAD LAMP LOWER BRACKET CLIP	Not Necessary	31.17 FL	*- FL
9	1		*FRONT O/S CORNER PANEL	Bent	446.14 FL	*446.14 FL
10	1		*FRONT O/S STEP PANEL GARNISH	Repair	244.92 FL	*- FL
11	1		*FRONT O/S DOOR	Distorted	3,465.47 FL	*3,196.70 FL
12	1		*FRONT O/S DOOR SIDE MIRROR COMP	Broken	3,212.98 FL	*2,907.30 FL
13	2		*FRONT O/S DOOR TOP & LOW HINGE	Bent / Twisted	331.58 FL	*331.58 FL
14	1		*FRONT O/S DOOR CHECKER	Twisted	278.50 FL	*278.50 FL
15	1		*FRONT O/S DOOR WEATHERSTRIP	Not Necessary	348.15 FL	*- FL
16	1		*FRONT O/S DOOR LOCK OUTER HANDLE	Grazed	260.60 FL	*260.60 FL
17	1		*FRONT O/S DOOR LOCK KNOB	Grazed	35.10 FL	*35.10 FL
18	1		*FRONT O/S DOOR GLASS REGULATOR	Not Necessary	386.40 FL	*- FL
19	16		*FRONT O/S DOOR TRIM BOARD CLIPS	Not Necessary	78.40 FL	*- FL
20	1		*FRONT O/S DOOR LOCK PILLAR PANEL	Cracked	761.20 FL	*761.20 FL
21	1		*FRONT O/S DOOR INNER LOCK	Damaged / Jammed	802.20 FL	*802.20 FL
22	1		*O/S SIDE DOOR	Cracked	3,949.10 FL	*3,221.20 FL
23	1		*O/S SIDE DOOR LOCK	Damaged / Jammed	355.30 FL	*355.30 FL
24	1		*O/S SIDE DOOR GLASS INNER SEAL	Necessary	98.80 FL	*98.80 FL
25	1		*O/S SIDE DOOR GLASS INNER DAMPER	Necessary	75.00 FL	*75.00 FL
26	1		*O/S SIDE DOOR GLASS SEALANT	Necessary	60.00 FN	*40.00 F
27	16		*O/S SIDE DOOR INNER TRIM BOARD CLIPS	Not Necessary	78.40 FL	*- FL
28	1		*FRONT O/S DOOR COMPANY STICKER	Necessary	80.00 FS	*30.00 FS
29	1		*FRONT O/S CORNER PANEL	Repeated	409.30 FL	*- FL
30	2		*FRONT O/S CORNER PANEL HOLDER BRACKET	Not Necessary	122.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	19,663.37	16,104.08
- List Item Discount on L Items 25.00/25.00% (S\$)	4,880.84	4,008.52
- Nett Item Discount on N Items 25.00/0.00% (S\$)	15.00	0.00
Total Parts (S\$)	14,767.53	12,095.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM, INCLUDING RADIO, REVERSE CAMERA & ADJUST HEADLIGHT ALIGNMENT	New	100.00	20.00
2	TO TRANSFER FRONT O/S DOOR TRIM BOARD, GLASS, MOULDING, CHANNEL, WEATHERSTRIP, LOCK, REGULATOR, MOTOR, HINGE, CHECKER, HANDLE & NECESSARY PARTS INTO NEW DOOR	New	200.00	60.00
3	TO REMOVE & REFIX O/S SIDE DOOR TRIM BOARD COVER, INNER LOCK, ROLLAR, BRACKET & NECESSARY PARTS	New	150.00	60.00
4	TO REMOVE & REFIX O/S SIDE DOOR GLASS & NECESSARY PARTS	New	150.00	100.00
5	TO REMOVE & REFIX FRONT O/S CUSHION SEAT, CARPET, FLOOR MAT, DOOR RUN CHANNEL, SAFETY BELT, ROOF LINING, UPHOLSTERY & NECESSARY PARTS, TO ENABLE REPAIR DOOR LOCK PILLAR PANEL	New	180.00	100.00
6	TO CHECK & ADJUST FRONT WHEEL ALIGNMENT & BALANCING	New	120.00	0.00
7	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT FRONT O/S WHEEL PANEL, FRONT O/S DOOR PILLAR PANEL & NECESSARY PARTS, TO WELD, RENEW & ALIGN ABOVE PARTS	New	2,000.00	1,000.00
8	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	2,000.00	1,100.00
Gross Labour Cost (\$\$)			4,900.00	2,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >