

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/11/24/20023/4vh3**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

G12L6599M

at Workshop m/s

hyundai 2-pm

of

Insured:

YN5132A

Policy No.

Claims No.

Sum Insured:

Excess:

600

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value:

877k.

IDAC Accident Rpt:

Consistent? : **Yes** or **No**

GIA / PR Seen:

Consistent? : **Yes** or **No**

Est. Repairs:

days

Res.:

Yes or **No**

Lum Sum:

1.3.1 %

3 Val.:

Yes or **No****CA / REV / REP. / 24 HRS**C 340M

Date:

Person Contacted:

Vehicle: IN / OUT
LTAG 22950

Veh No:

G12L6599M

Yr Regn:

28/12/21Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**

Truck / Trailer or

CA

Make:

Toyota hiace 2.0Dxc 1998

Colour

silver

A/C:

Insured / Std / NI / NA

Sp. Reading

125019

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

TRH 2000 347863Gen. Cond: **Good / Fair / Poor / Burnt**Steering: **Inorder / Jammed / Leaked / Burnt** orBrake: **Inorder / Jammed / Leaked / Burnt** orModi: **Nil / S/Rim / STD A/Rim** or

Tyre Size:

F:

195R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /**TOYO / YOKO** orGreenlander

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

01/12/24

D.O.I.

04/12/24

Survey held at

Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop** oro/s dr, o/s body.The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time

Action / Instruction

Dep 11k.

Date/Time, File Pass to?

: **Preli. Report**

1)

Date/Time, File Return to?

: **Final Report**

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

: **Site Insp (\$**: **Interview (\$**: **Tech. Invs (\$**: **Weekend (\$**

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

)

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 3163/12/24

Your Ref:

Date: 2nd December 2024

The Claim's Manager
Motor Claims Dept.
INDIA INTERNATIONAL INSURANCE PTE. LTD.
6, Raffles Quay, #22-00,
Singapore 048580

Name Of Insured : M/S DL Repair & Aircon Services Pte. Ltd.
Date Of Accident : 01/12/24 (23:45hrs)
Policy Number : D22MCV0010320_01

Estimate cost of repair to TOYOTA HIACE (A) 2.0 Van - GBL 6599 M

- 1 pc front grille Comp
- 1 pc front grille inner support base
- 6 pcs front grille clips & stopper
- 1 pc front bumper
- 1 pc front bumper o/s side bracket
- 10 pcs front bumper clips
- 1 pc o/s head lamp comp.
- 1 pc o/s head lamp lower bracket clip
- 1 pc front o/s corner panel
- 1 pc front o/s step panel garnish
- 1 pc front o/s door
- 1 pc front o/s door side mirror comp
- 2 pcs front o/s door top & low hinge
- 1 pc front o/s door checker
- 1 pc front o/s door weatherstrip
- 1 pc front o/s door lock outer handle
- 1 pc front o/s door lock knob
- 1 pc front o/s door glass regulator
- 16 pcs front o/s door trim board clips
- 1 pc front o/s door lock pillar panel
- 1 pc front o/s door inner lock
- 1 pc o/s side door
- 1 pc o/s side door lock
- 1 pc o/s side door glass inner seal
- 1 pc o/s side door glass inner damper
- 1 pc o/s side door glass sealant
- 16 pcs o/s side door inner trim board clips

cm \$ 546.70 ✓
 11 488.20 X
 @ \$ 14.60 cm 87.60 ✓
 D.S 942.00 ✓
 cm 238.06 ✓
 @ \$ 6.00 cm 60.00 ✓
 cm 1,390.10 ✓
 11 31.17 X
 sum 446.14 ✓
 2 244.92 X
 D.S 3,465.47 ✓
 sum 3,212.98 ✓
 @ \$ 165.79 331.58 ?
 278.50 ?
 348.15 ?
 sum 260.60 ✓
 sum 35.10 ✓
 11 386.40 X
 @ \$ 4.90 11 78.40 X
 cm 761.20 ✓
 802.20 ?
 cm 3,949.10 ✓
 355.30 ?
 cm 98.80 ✓
 cm 75.00 ✓
 cm 60.00 4051N
 @ \$ 4.90 11 78.40 X

\$ 19,052.07
 Less 25% \$ 4,763.02

\$ 14,289.05

cm 80.00 S.N

1 pc front o/s door company sticker

To wiring check up for affected wiring system, including
radio, reverse camera & adjust headlight alignment.

100.00 20

\$ 14,469.05

Balance C/F.....

27910-26A60

Supplementary Bill B/H

not Affected
 motor
 Expenses 8600
 4/12/24
 p/r 4
 7 days.

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 3163/12/24

Your Ref: _____

Date: 4th DEC 2024

The Claim's Manager
Motor Claims Dept.
INDIA INTERNATIONAL INSURANCE PTE. LTD.
6, Raffles Quay, #22-00,
Singapore 048580

Name of Insured : M/S DL Repair & Aircon Services Pte. Ltd.
Date of Accident : 01/12/24 (23:45hrs)
Policy Number : D22MCV0010320_01

Supplementary Bill for TOYOTA HIACE (A) 2.0 Van - GBL 6599 M

1 pc front o/s corner panel		507 \$	409.30 ✓
2 pcs front o/s corner panel holder bracket	61.00	17 \$	122.00 X

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 3163/12/24 Your Ref: Date: 2nd December 2024

M/S INDIA INTERNATIONAL INSURANCE PTE. LTD.,

Balance B/F.... \$ 14,469.05

To transfer front o/s door trim board, glass, moulding, channel, weatherstrip, lock, regulator, motor, hinge, checker, handle & necessary parts into new door.	200.00 60
To remove & refix o/s side door trim board cover, inner lock, roller, bracket & necessary parts.	150.00 60
To remove & refix o/s side door glass & necessary parts.	150.00 100
To remove & refix front o/s cushion seat, carpet, floor mat, door run channel, safety belt, roof lining, upholstery & necessary parts, to enable repair door lock pillar panel.	180.00 100
To check & adjust front wheel alignment & balancing.	120.00 X
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front o/s wheel panel, front o/s door pillar panel & necessary parts, to weld, renew & align above parts.	1000 2,000.00
To putty & respray painting on all affected accident parts.	1000 2,000.00
	\$ 19,089.05 =====

Dollars : Nineteen Thousand Eighty Nine And Cents Five Only.

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hereby notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts, for a survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-approved and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: