



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 3294T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TOW CARRIER	BENT	4,800.00	3,800.00
1	REAR TOW CARRIER HYDRAULIC HOSE (DISCHARGE)	NOT NECESSARY	450.00	-
1	REAR TOW CARRIER HYDRAULIC HOSE (RETURN)	NOT NECESSARY	450.00	-
1	REAR TOW CARRIER LOCK PIN	NOT NECESSARY	400.00	-
			6,100.00	3,800.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR TOW CARRIER HYDRAULIC PUMP (LOCAL REPAIR) (SN)	DAMAGED	4,800.00	800.00
			4,800.00	800.00
	<u>LABOUR</u>			
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,500.00	800.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		2,000.00	600.00
			3,500.00	1,400.00
	GRAND TOTAL		14,400.00	6,000.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,100.00

Report Ref No. CS/LIP24120026/Avh3m4(N)

MARKET VALUE: \$32,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$690.00=NETT VALUE: \$31,310.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.