

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CS/AIG24060310/AVP3E2**Date:** 28/08/2024REFERENCE

Insured/Claimant:	AWFULLYCHOCOLATE PTE LTD	Policy No:	7210065355
Date of Loss:	26/06/2024	Nature of Claim:	OD Claim No: 9340797409SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKJ2200T		
Make & Model:	AUDI Q7, 2.0 TFSI QU (A)	Engine No:	CYR103508
Reg. Date:	28/06/2021 (Man. Year: 2020)	Chassis No:	WAUZZZ4M0MD010750
Colour:	Black	Odometer:	48970 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$280,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/55 R19	Rear Tyre Size:	255/55 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,387.00	1,053.60	9,333.40	89.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,840.00	2,852.00	988.00	25.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,227.00	3,905.60	10,321.40	72.55
- Excess (\$\$)	1,000.00	1,000.00	0.00	0.00
(\$\$)	13,227.00	2,905.60	10,321.40	78.03
+ GST 9.00/9.00% (\$\$)	1,190.43	261.50	928.93	78.03
Nett Amount (\$\$)	14,417.43	3,167.10	11,250.33	78.03

INSPECTION

Date of Assignment:	01/07/2024		
Date Inspected:	03/07/2024	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER - UPPER	Repair	1,641.00 FS	*- FS
2	1		*REAR BUMPER - LOWER	Repair	2,307.00 FS	*- FS
3	1		*REAR BUMPER FIXING PARTS	Not Necessary	490.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Not Necessary	1,580.00 FS	*- FS
5	1		*REAR REINFORCEMENT BEAM	Not Necessary	1,729.00 FS	*- FS
6	2		*REAR REINFORCEMENT BEAM SEAL	Not Necessary	36.00 FS	*- FS
7	1		*REAR BUMPER HOLDING STRAP	Not Necessary	231.00 FS	*- FS
8	1		*REAR BUMPER GUIDE SECTION - CENTER	Not Necessary	178.00 FS	*- FS
9	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	80.00 FS	*- FS
10	1		*REAR BUMPER TAILLIGHT - RH	Cracked	452.00 FS	*361.60 FS
11	1		*REAR PARKING AID SENSOR	Not Necessary	286.00 FS	*- FS
12	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	11.00 FS	*- FS
13	2		*REAR WHEEL ARCH COVER - LH / RH	Necessary	866.00 FS	*692.00 FS
14	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)

10,387.00

1,053.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,000.00	600.00
3	TO RESPRAY REAR BUMPER, REAR LOWER BUMPER AND BOTH REAR WHEELARCH TRIMS	New	2,000.00	1,600.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	480.00	292.00
Gross Labour Cost (S\$)			3,840.00	2,852.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >