

Not Authorized
new
3/12/24
2/5 4000/
the sha agency

4 days

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No. : SLL9836R
Chassis No. : RU11200814
Engine No. : L15B4400814
Date of Accident : 28.11.2024

Reference No. : 241128-TPC-JSSM08
Make/Model : HONDA / VEZEL
Date : 05.11.2024

Replacement of Damaged Parts

S/No.	QTY	Description	Condition / Remarks	Repairer's Estimates
1	1	Front LH Door	Damaged 1/1	\$ 1,677.00
2	1	Front LH Door Hinge Upper	Buckled 1/1	\$ 355.00
3	1	Front LH Door Hinge Lower	Buckled 1/1	\$ 355.00
4	1	Front LH Fender	Damaged 2/24	\$ 878.00
5	1	Front LH Fender Garnish	Damaged 5 new	\$ 455.00
6	10	Front LH Fender Garnish Clips	Necessary 1/1	\$ 60.00
7	1	Front LH Side Skirt	Damaged 9 new	\$ 910.00
8	1	Rear LH Door	Damaged 20/24	\$ 1,677.00
9	1	Rear LH Door Weather Seal	Torn 1/1	\$ 390.00
10	1	Front Alloy Sport Rims	Scratched 1/1	\$ 1,250.00
11	1	Front PW Motor	Faulty 2/2	\$ 455.00
12	1	Front PW Motor Switch	Faulty 1/1	\$ 490.00
13	1	Front PW Motor Rack regulator	Distorted 3/11	\$ 670.00
14	1	Front Door Lock	Impacted 1/1	\$ 535.00
				\$ 10,157.00

Total (Parts): \$ 10,157.00

-20% \$ 8,125.60

Labour Charges

15	To fix & dismantle and remove damaged Fron to Rear Left Portions; affected damaged portion.	\$ 1,000.00
16	To apply anti rust coat and affected areas	\$ -
17	To check wiring	\$ 120.00
18	Welding and cutting of affected panels, including chassis alignment.	\$ -
19	Spray painting for Rear Portions affected parts	\$ 1,200.00
20	Programming for Hybrid System Reset	\$ -
21	Diagnose ECU system and reset error code.	\$ -
22	3D Wheel Alignment	\$ 120.00
23	To Apply Waterproofing sealer on End and Front Support Panels	\$ -

Total Labour: \$ 2,440.00

Total cost of repairs (Total cost of parts + Total Labour Cost) \$ 10,565.60

Less 20% \$ 8,452.48

JSSM AUTOSOLUTIONS PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 1

P-4294-50
202
3435-60
480
1090
5005-6
203
4004