



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNN 5335L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	871.20	-
1	FRONT BUMPER LOWER LID	CUT	440.90	440.90
2	FRONT BUMPER SIDE RETAINER L/R @\$22.50	NOT NECESSARY	45.00	-
1	FRONT RH DOOR SIDE MIRROR	CUT	1,554.70	1,180.00
1	FRONT RH DOOR SIDE MIRROR COVER	NOT NECESSARY	89.70	-
1	FRONT RH FENDER	TO REPAIR SEE LABOUR	785.20	-
1	FRONT RH FENDER ARCH GARNISH	CUT	198.20	198.20
1	FRONT RH FENDER INNER SHIELD	NOT NECESSARY	138.20	-
1	FRONT RH HEADLAMP	CUT	2,150.70	2,150.70
1	FRONT RH KNUCKLE ARM	NOT NECESSARY	335.80	-
1	FRONT RH KNUCKLE ARM BEARING	DAMAGED	168.90	168.90
1	FRONT RH LOWER ARM	NOT NECESSARY	398.70	-
1	FRONT RH SHOCK ABSORBER	NOT NECESSARY	316.90	-
1	FRONT RH STABILIZER LINK	NOT NECESSARY	98.70	-
	LESS 20% DISCOUNT		-1,518.56	-827.74
			6,074.24	3,310.96
1	FRONT RH SPORT RIM (SN)	CUT	926.40	550.00
	LESS 20% DISCOUNT		-185.28	-
			741.12	550.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER CLIPS (SN)	NOT NECESSARY	80.00	-
1	SET FRONT RH FENDER ARCH GARNISH CLIPS (SN)	NECESSARY	40.00	30.00
1	SET FRONT RH FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	40.00	-
1	FRONT RH TYRE 215/60R16 (SN)	NOT NECESSARY	500.00	-
			660.00	30.00

Report Ref No. CS/INC24120030/Aqh3m4(N)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING. (TO FR).		80.00	30.00
	TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION.		300.00	80.00
	TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL ALIGNMENTS SYSTEM.		100.00	80.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	500.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT RH FENDER.		900.00	200.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	30.00
			2,500.00	920.00
	<b>GRAND TOTAL</b>		<b>9,975.36</b>	<b>4,810.96</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>3,800.00</b>

Report Ref No. CS/INC24120030/Aqh3m4(N)

TOTAL FOR SPARE PARTS: \$ 7,475.36 \$ 3,890.96

TOTAL FOR LABOUR : \$ 2,500.00 \$ 920.00

TOTAL REPAIR COST: \$ 9,975.36 \$ 4,810.96

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.