

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	ICE LTD		Ref:	CS/INC24120032/Anh3e2(N)	
	75 BRAS BASAH FINCOME CENTRE	ROAD SINGAPORE 189557		Date:	17/01/2025	
	ATTN: AZHARI AF	IDI		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SCA 338K	Veh. Inspected		SLN 8322C	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1306784-001	Excess (\$)		0.00	
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		03/12/2024	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA HRV	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	JHMRU1810GX202475	Colour		GREEN	
	Odometer	154278 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	DAVANTI		6 mm	
	L/H Front Tyre	215/60 R16	DAVANTI		6 mm	
	R/H Rear Tyre	215/60 R16	DAVANTI		6 mm	
	L/H Rear Tyre	215/60 R16	DAVANTI		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	01/12/2024	Inspect Date /	Time	03/12/2024 (03:49 PM)	
	Survey held at	RYDER AUTO PTE LTD				
		2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921				
5a.	5a. Remarks					
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days					