

AB ENGINEERING PTE LTD

Co. Reg No: 202117273R

10 KAKI BUKIT ROAD 2 #01-25, FIRST EAST CENTRE, SINGAPORE 417868

Tel : 8858 6282

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: GBL1064Y

Report No :

Chassis No:

Engine No:

Date : 11/29/2024

MAKE: TOYOTA

MODEL : HIACE VAN TURBO 5DR MT

TYPE : COMMERCIAL

Replacement of Damaged Parts

S/No.	Description	Qty	Our Recommendation
1	Tail Lamp RH / RR	1	367.70
2	Rear bumper / RR	1	545.80
3	Rear bumper clips / RR	10	55.00
4	Rear bumper retainer - RH / RR	1	46.00
5	Cover, rear bumper, upper - RH / RR	1	101.20
6	Cover, rear bumper, upper retainer - RH X AN	1	41.60
7	Rear Fender Door - RH X R	1	\$1,675.00

Less 25% 1090.70
Total (P) \$708.08 -25%
\$2,124.23 818.02

Total (Parts & S/N): \$2,124.23

Labour Charges

- * To check wiring. \$100.00 30
- To dismantle and replace of the accident damaged parts; to heat/weld, cut-off rear fender door, rear bumper, tail lamp & cover rear bumper etc including knocking, repair, reshape and adjust of same. \$800.00 400
- * To putty and spray painting on rear fender door, rear bumper & rear cover & accident panels including knocking, repair, reshape and adjust of same. \$1,000.00 500
- * To apply rustproofing on the repaired and replaced panels. \$300.00 30

Total Labour: \$2,200.00 960

Final Repair Cost to Vehicle No : GBL1064Y

Amount	\$4,324.23
Lump Sum Discount -20%	\$864.85
Total	\$3,459.38
Add GST 9%	\$311.34
Grand Total	\$3,770.72

1,778.02

L/S - 1,422.42
= 1400

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve (LKK)
3/12/24, 11.00 am
w R
L/S
y AL sig
4 days