



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

ATTN: YEE PEI LI

Ref: CS/INC24120035/Eqh3m4(N)

Date: 15/01/2025

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLK 9362X	Veh. Inspected	GBL 1064Y
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1306635-001	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	03/12/2024

#### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	JTFHT02P600251584	Colour	SILVER
Odometer	118385 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195R15C	DIAMONDBACK	5 mm
L/H Front Tyre	195R15C	DIAMONDBACK	5 mm
R/H Rear Tyre	195R15C	DIAMONDBACK	5 mm
L/H Rear Tyre	195R15C	DIAMONDBACK	5 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.  
DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	04/11/2024	Inspect Date / Time	03/12/2024 ( 10:38 AM )
Survey held at	10 KAKI BUKIT AVE 2 #01-19 KAKI BUKIT AUTOHUB		
Repairer	AB ENGINEERING PTE LTD		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days