

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24120036/UQH3M4
Date: 26/06/2025REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	MCV23B00036800
Claimant Vehicle No :	YP5667M	Insured Vehicle No :	YQ5432T
Date of Loss:	29/11/2024	Nature of Claim:	TP
		Claim No:	DMCV2400270H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP5667M		
Make & Model:	mitsubishi canter, 3.0 D FEB21ER4SDEB (CBU) (M)	Engine No:	4P10C40371
Reg. Date:	21/02/2017 (Man. Year: 2016)	Chassis No:	FEB21EA21190
Colour:	White	Odometer:	350950 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/85R15	Rear Tyre Size:	195/85R15 (D)
Front Left Side:	Delium 5 mm	Rear Left Side:	Yokohama 5/5 mm
Front Right Side:	Delium 5 mm	Rear Right Side:	Yokohama 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,204.25	3,290.75	2,913.50	46.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,430.00	1,150.00	1,280.00	52.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,634.25	4,440.75	4,193.50	48.57
Approved Total (Overridden) (S\$)		3,500.00		
Nett Amount (S\$)	8,634.25	3,500.00	5,134.25	59.46

INSPECTION

Date of Assignment:	03/12/2024		
Date Inspected:	03/12/2024	Inspected At:	ZOOM AUTOWERKS PTE LTD 15 KAKI BUKIT RD 4 #01-53 BARTLEY BIZ CENTRE SINGAPORE 417808
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Jun 2025)	
Parts:	N/A	MITSUBISHI CANTER 3.0 D FEB21ER4SDEB (CBU) (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP5667M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented/Bent	2,201.00 FL	*2,201.00 FL
2	1		*TAILGATE LOWER MEMBER	Bent	680.00 FL	*680.00 FL
3	1		*DROP SIDEGATE O/S	Repair	2,998.00 FL	*- FL
4	1		*TAILLAMP O/S	Cracked	280.00 FL	*280.00 FL
5	1		*REAR LICENCE PLATE	Not Necessary	15.00 FS	*- FS
6	1		*SET TAILGATE 60 KM/H & 20 PAX STICKER	Necessary	20.00 FS	*20.00 FS
7	1		*REAR STOPPER RUBBER O/S	Torn	50.00 FS	*50.00 FS
8	1		*REAR STEP PANEL	Bent	500.00 FS	*250.00 FS
9	1		*REAR SAFETY BAR	Bent	1,000.00 FS	*600.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,744.00	4,081.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,539.75	790.25
Total Parts (\$\$)	6,204.25	3,290.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	100.00	30.00
3	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,080.00	600.00
4	TO PUTTY & SPRAY PAINTING	New	1,200.00	500.00
			Gross Labour Cost (\$)	1,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >