



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24120042/Evh3e2
16 RAFFLES QUAY	Date:	30/12/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 4221L	Veh. Inspected	SBL 5400J
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24010525MFCT	Excess	\$0.00
Assign From	HARMINDER KAUR	Assign Date	03/12/2024

2. Vehicle Details

Make & Model	HONDA CRV	C.C	1498
Engine No.	L15BG1115683	Year of Reg.	12/03/2018
Chassis No.	MRHRW1880JP000059	Colour	WHITE
Odometer	115870 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/60 R18	BRIDGESTONE	6
L/H Front Tyre	235/60 R18	BRIDGESTONE	6
R/H Rear Tyre	235/60 R18	BRIDGESTONE	6
L/H Rear Tyre	235/60 R18	BRIDGESTONE	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/11/2024	Inspection Date	16/12/2024
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days