



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNE 7773P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT (DENTED)	NOT CONSISTENT WITH THE IMPACT (OLD DAMAGED)	1,193.10	-
1	WINDSCREEN MOULDING (REAR)	NOT NECESSARY	108.60	-
1	LOGO (H)	NOT NECESSARY	42.90	-
1	EMBLEM (SHUTTLE)	NOT NECESSARY	61.80	-
1	EMBLEM (HYBRID)	NOT NECESSARY	64.50	-
1	REAR BOOT GARNISH (CHROME)	NOT NECESSARY	451.30	-
1	REAR BOOT INNER TRIM BOARD	NOT NECESSARY	242.50	-
12	REAR BOOT INNER TRIM BOARD CLIPS @\$4.50	NOT NECESSARY	54.00	-
2	REAR BOOT ADJUSTER RUBBER @\$9.20	NOT NECESSARY	18.40	-
1	REAR BOOT INNER LOCK	NOT NECESSARY	172.70	-
1	REAR BOOT LOCK STRIKER	NOT NECESSARY	36.70	-
1	REAR BOOT WEATHERSTRIP	NOT NECESSARY	185.50	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	504.40	-
1	REAR END PANEL GARNISH	NOT NECESSARY	170.20	-
1	SENSOR (KEY)	NOT NECESSARY	75.10	-
1	REAR BUMPER	DEFORMED / TORN	1,150.60	1,150.60
6	BUMPER CLIP @\$5.20	NECESSARY	31.20	31.20
2	REAR BUMPER SPONGE @\$101.50	NOT NECESSARY	203.00	-
1	BUMPER SIDE RETAINER (L/H/R)	NOT NECESSARY	18.90	-
1	BUMPER SIDE RETAINER (R/H/R)	NOT NECESSARY	18.90	-
1	BUMPER CAP	NOT NECESSARY	25.50	-
	LESS 20% DISCOUNT		-965.96	-236.36
			3,863.84	945.44
<u>SPECIAL NETT ITEMS</u>				
1	SEALANT (WINDSCREEN) (SN)	NOT NECESSARY	35.00	-
1	BTL REAR END PANEL SEALANT (SN)	NOT NECESSARY	50.00	-
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	35.00	-
			120.00	-

Report Ref No. CS/AGI24120044/Unh3e2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEAT & REPAIR REAR DAMAGE. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,000.00	300.00
	TO PUTTY AND RE-SPRAY AFFECTED PORTION.		900.00	400.00
	TO PROVIDE UNDER TURFCODE.	NOT NECESSARY	180.00	-
	TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS.		50.00	20.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT COMPONENTS / FACILITATE THE REPAIR.	NOT NECESSARY	150.00	-
	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT.	REPEATED	80.00	-
	TO TRANSFER REAR BOOT FITTING.	NOT NECESSARY	120.00	-
			2,630.00	720.00
	GRAND TOTAL		6,613.84	1,665.44
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,300.00

Report Ref No. CS/AGI24120044/Unh3e2(N)

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.