

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24070002/TPA3Q2**Date:** 19/09/2024REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100435443-08
Claimant Vehicle No : SKV6006Z **Insured Vehicle No :** SKW3157K
 Date of Loss: 26/06/2024 Nature of Claim: TP Claim No: 5580003965SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKV6006Z**
 Make & Model: AUDI A3, 1.4 TFSI (A) Engine No: CZC261319
 Reg. Date: 25/09/2015 (Man. Year: 2015) Chassis No: WAUZZZ8V5F1140370
 Colour: Red Odometer: 81824 km
 Engine Capacity: 1395 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,799.00	0.00	4,799.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,760.00	1,622.00	1,138.00	41.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,559.00	1,622.00	5,937.00	78.54
+ GST 9.00/9.00% (S\$)	680.31	145.98	534.33	78.54
Nett Amount (S\$)	8,239.31	1,767.98	6,471.33	78.54
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		1,920.16		

INSPECTION

Date of Assignment: 02/07/2024
 Date Inspected: 02/07/2024 Inspected At: Premium Automobiles Pte Ltd (HQ)
 55 UBI ROAD 1
 Singapore 408699
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	2,483.00 F	*- F
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	216.00 F	*- F
3	2		*REAR BUMPER GUIDE SECTION - LH / RH	Not Necessary	42.00 F	*- F
4	2		*REAR BUMPER GUIDE SECTION PIN - LH / RH	Not Necessary	75.00 F	*- F
5	1		*REAR BUMPER SPOILER	Not Necessary	297.00 F	*- F
6	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	736.00 F	*- F
7	2		*REAR BUMPER LOWER BRACKET - LH / RH	Not Necessary	34.00 F	*- F
8	1		*REAR PARKING AID SENSOR	Not Necessary	572.00 F	*- F
9	1		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	44.00 F	*- F
10	1		*SUNDRIES	Not Necessary	300.00 F	*- F
F=Franchise part.						
					Total Parts (\$)	4,799.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER PARKING AID.	New	280.00	280.00
2	TO DISMANTLE AND RENEW BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS	New	1,000.00	500.00
3	TO RESPRAY REAR BUMPER	New	1,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	480.00	292.00
Gross Labour Cost (\$\$)			2,760.00	1,622.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >