

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24120048/UVH3E2
Date: 30/12/2024**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001925801
Claimant Vehicle No :	SMP6594A	Insured Vehicle No :	F131Z
Date of Loss:	03/12/2024	Nature of Claim:	TP
		Claim No:	383040

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP6594A	Engine No:	2ZR0D65721
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Chassis No:	ZWR800387227
Reg. Date:	07/10/2019 (Man. Year: 2019)	Odometer:	140984 km
Colour:	Black		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Giti 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,599.07	6,039.70	2,559.37	29.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	1,020.00	910.00	47.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,529.07	7,059.70	3,469.37	32.95
Approved Total (Overridden) (S\$)		5,600.00		
Nett Amount (S\$)	10,529.07	5,600.00	4,929.07	46.81

INSPECTION

Date of Assignment:	04/12/2024	
Date Inspected:	04/12/2024	Inspected At: T K Lee Automotive Pte Ltd (HQ) NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Dec 2024)
Parts:	M1-MPV	TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP6594A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Torn	1,210.66 FL	*1,210.66 FL
2	1		*FRONT BUMPER LOWER GRILLE - CTR	Serviceable	181.93 FL	*- FL
3	1		*FRONT BUMPER FOG LAMP - LH	Serviceable	341.65 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP COVER - LH	Torn	110.25 FL	*110.25 FL
5	1		*FRONT BUMPER SPONGE	Torn	180.93 FL	*180.93 FL
6	1		*FRONT BUMPER REINFORCEMENT	Bent	599.62 FL	*599.62 FL
7	2		*FRONT BUMPER SIDE RETAINERS - R/L	Not Necessary	220.50 FL	*- FL
8	1		*FRONT BUMPER UNDERCOVER	Not Necessary	180.93 FL	*- FL
9	1		*FRONT FENDER - LH	Repair	861.13 FL	*- FL
10	1		*FRONT FENDER INNER SHIELD - LH	Not Necessary	154.43 FL	*- FL
11	1		*FRONT HEADLAMP ASSY - LH	Cracked	2,889.65 FL	*2,889.65 FL
12	1		*FRONT SUPPORT PANEL	Repair	1,160.50 FL	*- FL
13	1		*RAD GRILLE - TOP	Cracked	1,101.63 FL	*1,101.63 FL
14	1		*RAD GRILLE - BOTTOM	Cracked	991.62 FL	*800.20 FL
15	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
16	1		*FRONT BUMPER LOWER SPOILER	Deformed / Torn	850.00 FS	*800.00 FS
17	1		*SET FRONT NUMBER PLATE	Cracked	60.00 FS	*40.00 FS
					Sub Total (\$\$)	11,145.43 7,762.94
					- List Item Discount on L Items 25.00/25.00% (\$\$)	2,546.36 1,723.24
					Total Parts (\$\$)	8,599.07 6,039.70

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT ELECTRICAL WIRING	New	50.00	20.00
2	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	New	1,080.00	600.00
3	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	New	800.00	400.00
Gross Labour Cost (\$)			1,930.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >