

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	ETHOZ PROTECT F		Ref:	CS/TP24120055/Tnh3e2	
			Date:	16/12/2024	
	658075		Code:	TP513	
1.		Policy Particulars :- T			
••	Insured Veh.	-	Veh. Inspected	GBH 9042D	
	Policy No.		Coverage	0	
	Claim No.	_	Excess	\$0.00	
	Assign From		Assign Date	04/12/2024	
2.	/ toolgii i rom	Vehicle		0171272021	
	Make & Model	TOYOTA HIACE	c.c	2982	
	Engine No.	1KD2829658	Year of Reg.	25/10/2018	
	Chassis No.	JTFHT02P300245905	Colour	WHITE	
	Odometer	223178 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: NIL			
3.	3. Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	195 R15	FIRENZA	6	
	L/H Front Tyre	195 R15	FIRENZA	6	
	R/H Rear Tyre	195 R15	FIRENZA	6	
	L/H Rear Tyre	195 R15	FIRENZA	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.					
DAMAGES SEE DETAILS.					
5.	5. General Information				
	Accident Date	26/11/2024	Inspection Date	04/12/2024	
	Survey held at	ETHOZ GROUP LTD - 18 PANDAN RO	DAD SINGAPORE (609270	
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days