



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24120060/Unh3m4
16 RAFFLES QUAY	Date:	16/12/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 7817Y	Veh. Inspected	GBM 7443S
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24010613MFCT	Excess	\$0.00
Assign From	TEO SWEE KEONG	Assign Date	04/12/2024

2. Vehicle Details

Make & Model	TOYOTA HIACE (A)	C.C	2755
Engine No.	1GD9392355	Year of Reg.	22/10/2024
Chassis No.	JTFHA02P508005505	Colour	WHITE
Odometer	4848 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/80R15	BRIDGESTONE	8
L/H Front Tyre	195/80R15	BRIDGESTONE	8
R/H Rear Tyre	195/80R15	BRIDGESTONE	8
L/H Rear Tyre	195/80R15	BRIDGESTONE	8

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/12/2024	Inspection Date	05/12/2024
Survey held at	CARSMITH PTE LTD - 8 KAKI BUKIT AVE 4 #04-35 PREMIER@KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days