



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

ATTN: RAJESWARY

Ref: CS/INC24120067/Anh3e2(N)

Date: 28/02/2025

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMK 6864Y	Veh. Inspected	SMK 5762P
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1306954-001	Excess (\$)	0.00
Assign From	RAJESWARY	Assign Date	05/12/2024

#### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA LEXUS IS250	c.c	2500
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JTHBK262405106721	Colour	BLACK
Odometer	300054 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	255/35 R18	MICHELIN	6 mm
L/H Front Tyre	255/35 R18	MICHELIN	6 mm
R/H Rear Tyre	255/35 R18	MICHELIN	6 mm
L/H Rear Tyre	255/35 R18	MICHELIN	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	30/11/2024	Inspect Date / Time	04/12/2024 ( 02:37 PM )
Survey held at	ELITE AUTO RESTORATION PTE LTD 23 KAKI BUKIT AVE 4 #04-01, AAS KAKI BUKIT CENTRE SINGAPORE 415933		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days