

ASS. REC. BY:

REF:

C7224120070/Kqh3

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$113K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 1.61 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMU 9537U Yr Regn: 09, 20Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mer A200 C.C. 1332Colour: White A/C: Insured / Std / NI / NASp. Reading: 126146 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WIK1771872J 239539Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD A/Rlm orTyre Size: F: 225/45R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 15/11/24

Rear

R/Bal. 8 mmL/Bal. 8 mmD.O.I. 5/12/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/12 @ 4154.20 Carbur (Red & 6793, 67%)

Date/Time, File Pass to?

☐ : Prel. Report

1) 19/12 19/12/24

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trlp: 1

Survey Fee:

Transportation

S + RS. \$

Fees

Others

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

E2Claims - W

Lump Sum T.I.B.I. (\$)

4154.20

TOTAL



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE P1

1 GATEWAY DRIVE #15-08
WESTGATE TOWER
SINGAPORE 608531

TEL :

ATTN : ACCOUNTS DEPT

FAX : *Not Authorised*

Recovery 34 parts

4 days

8 4154.20

ESTIMATE

NO : QUOT202412-000009(00)

DATE : 04/12/2024

POLICY NO : SP2003907937

VEH REG NO : SMU9537U

MAKE/MODEL : MERCEDES BENZ A200
SALOON PROGRESSIVE (R18
LED)

CHASSIS NO : W1K1771872J239539

ENGINE NO : 28291480402483

REG. DATE : 2020

YOUR REF NO : GBH8053D

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE

ACCIDENT DATE : 15/11/2024

TP VEH REG NO : GBH8053D

Estimate Repair Cost to Vehicle No : SMU9537U

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Bootlid	1	3,190.00	3,190.00 X
2 Bootlid 'A200' emblem	1	168.00	168.00 ✓
3 Bootlid centre logo	1	73.00	73.00 ✓
4 Bootlid weatherstrip	1	236.00	236.00 X
5 Rear end panel	1	1,298.00	1,298.00 X
6 Rear end panel top garnish	1	102.00	102.00 X
7 Rear bumper	1	1,625.00	1,625.00 ✓
8 Rear bumper reinforcement	1	605.00	605.00 2
9 Rear bumper inner frame	1	108.00	108.00 X
10 Rear bumper sensor	2	216.00	432.00 X
11 Rear bumper sensor seals	6	12.00	72.00 ✓
12 Rear bumper clips	15	10.00	150.00 60/1
13 Rear bumper lower garnish	1	595.00	595.00 ✓
14 Rear bumper centre chrome	1	350.00	350.00 2
			9,004.00
		Less 10%	896.80
			8,107.20
SPECIAL NET			
15 Bootlid 'C&C' emblem	1	40.00	40.00 ✓
			40.00
LABOUR			
16 To transfer damaged bootlid interior mechanism to new bootlid	1	120.00	120.00 X
17 To check & rectify wiring system	1	80.00	80.00 15/
18 To remove & refit rear bumper sensor	1	100.00	100.00 60/
19 To remove & fix rear interior garnishes & trimboard to facilitate the repairs	1	180.00	180.00 X
20 To panel beat and straighten rear chassis frame, rear floorboard panel, to cut & weld rear end panel, including replacement of parts and align where necessary, to refit & adjust the same	1	1,200.00	1,200.00 400/
21 To putty & spray on affected areas	1	1,000.00	1,000.00 440/
22 To apply rust-proofing on repaired and replaced panels	1	120.00	120.00 X
			2,800.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE P1

1 GATEWAY DRIVE #15-08

WESTGATE TOWER

SINGAPORE 608531

TEL :

FAX :

ATTN : ACCOUNTS DEPT

ESTIMATE

NO : QUOT202412-000009(00)

DATE : 04/12/2024

POLICY NO : SP2003907937

VEH REG NO : SMU9537U

MAKE/MODEL : MERCEDES BENZ A200
SALOON PROGRESSIVE (R18
LED)

CHASSIS NO : W1K1771872J239539

ENGINE NO : 28291480402483

REG. DATE : 2020

YOUR REF NO : GBH8053D

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE

ACCIDENT DATE : 15/11/2024

TP VEH REG NO : GBH8053D

Estimate Repair Cost to Vehicle No : SMU9537U

Description	Quantity	Unit Price	Amount
		S\$	S\$
		TOTAL	S\$ 10,947.20
		ADD GST @ 9.00%	985.27
		GRAND TOTAL	S\$ 11,932.47

SINGAPORE DOLLAR ELEVEN THOUSAND NINE HUNDRED THIRTY-TWO AND CENTS FORTY-SEVEN ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE