

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/AIG24120071/APA3Q2
Date: 15/05/2025

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220033900
Claimant Vehicle No :	SNS9884R	Insured Vehicle No :	GBL7513D
Date of Loss:	30/11/2024	Nature of Claim:	TP
		Claim No:	7865585703SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNS9884R	Engine No:	LEB7743841
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Chassis No:	GB73261325
Reg. Date:	09/09/2024 (Man. Year: 2024)	Odometer:	7424 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,746.00	7,292.96	7,453.04	50.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,580.00	1,500.00	3,080.00	67.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,326.00	8,792.96	10,533.04	54.50
Approved Total (Overridden) (S\$)		7,000.00		
(S\$)	19,326.00	7,000.00	12,326.00	63.78
+ GST 9.00/9.00% (S\$)	1,739.34	630.00	1,109.34	63.78
Nett Amount (S\$)	21,065.34	7,630.00	13,435.34	63.78
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		7,992.18		

INSPECTION

Date of Assignment:	05/12/2024		
Date Inspected:	05/12/2024	Inspected At:	Elite Auto Restoration Pte Ltd (HQ) No 23 Kaki Bukit Ave 4, #04-01 Singapore 415933
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	541.80 FL	*541.80 FL
2	2		*BONNET HINGES	Bent	171.20 FL	*171.20 FL
3	1		*BONNET INSULATOR	Not Necessary	105.70 FL	*- FL
4	2		*BONNET INNER RUBBER	Not Necessary	73.00 FL	*- FL
5	1		*BONNET LOCK	Not Necessary	153.40 FL	*- FL
6	1		*FRONT WIPER SIDE GARNISH RH	Not Necessary	240.90 FL	*- FL
7	1		*FRONT WINDSCREEN MOULDING RH	Not Necessary	187.90 FL	*- FL
8	1		*FRONT FENDER QUARTER GLASS W/MOULDING	Not Necessary	390.80 FL	*- FL
9	1		*FRONT BUMPER	Distorted	897.60 FL	*897.60 FL
10	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	90.00 FL	*- FL
11	1		*FRONT BUMPER REINFORCEMENT	Dented	386.90 FL	*386.90 FL
12	1		*FRONT BUMPER CENTER COVER	Not Necessary	198.30 FL	*- FL
13	1		*FRONT BUMPER TOW COVER	Not Necessary	42.30 FL	*- FL
14	1		*FRONT BUMPER SIDE GRILLE	N/S Cut	181.00 FL	*90.50 FL
15	1		*FRONT BUMPER FOG LAMP COVERS	N/S Cut	574.40 FL	*287.20 FL
16	1		*FRONT BUMPER LOWER GRILLE	Cut	165.70 FL	*165.70 FL
17	1		*FRONT BUMPER LOWER RUBBER	Not Necessary	75.80 FL	*- FL
18	1		*FRONT RADAR SENSOR	Not Necessary	1,023.40 FL	*- FL
19	1		*FRONT RADAR SENSOR BRACKET	Cracked	380.90 FL	*380.90 FL
20	1		*FRONT RADAR LOWER COVER	Not Necessary	38.70 FL	*- FL
21	1		*FRONT RADAR TOP COVER	Not Necessary	35.90 FL	*- FL
22	1		*FRONT GRILLE	Cracked	780.70 FL	*780.70 FL
23	1		*FRONT GRILLE BADGE	Necessary	85.00 FL	*85.00 FL
24	1		*FRONT GRILLE CHROME MOULDING	Cracked	124.30 FL	*124.30 FL
25	2		*FRONT GRILLE SIDE CHROME MOULDING	Not Necessary	186.40 FL	*- FL
26	2		*HEADLAMPS	Cracked	3,821.60 FL	*3,821.60 FL
27	2		*HEADLAMPS LOWER BACKET	Cracked	197.20 FL	*197.20 FL
28	2		*FRONT FENDERS	Repair	951.80 FL	*- FL
29	2		*FRONT FENDER INNER SHIELDS	Not Necessary	378.60 FL	*- FL
30	1		*FRONT FENDER BRACKET RH	Not Necessary	186.00 FL	*- FL
31	1		*FRONT FENDER EXTENSION PANEL RH	Repair	233.90 FL	*- FL
32	1		*FRONT CHASSIS FRAME MEMBERS	Not Necessary	580.60 FL	*- FL
33	1		*BRACE PANEL	Not Necessary	236.90 FL	*- FL
34	1		*SUPPORT PANEL	Repair	647.80 FL	*- FL
35	1		*SUPPORT TOP AIR DUCT	Not Necessary	148.40 FL	*- FL
36	2		*SUPPORT SIDE AIR GUIDE	Not Necessary	90.00 FL	*- FL
37	1		*RADIATOR	Not Necessary	1,502.60 FL	*- FL
38	1		*AIR CON CONDENSER	Dented	985.60 FL	*985.60 FL
39	1		*WIPER WASHER TANK	Not Necessary	89.50 FL	*- FL
40	1		*BONNET INSULATOR CLIPS	Not Necessary	60.00 FS	*- FS
41	1		*FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
42	2		*HEADLAMPS CLIPS	Not Necessary	120.00 FS	*- FS
43	1		*FRONT GRILLE CLIPS	Necessary	60.00 FS	*30.00 FS
44	2		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	120.00 FS	*- FS
45	1		*FRONT NUMBER PLATE W/HOLDER	Cracked	150.00 FS	*60.00 FS
46	1		*RADIATOR COOLANT	Necessary	150.00 FS	*40.00 FS
47	1		*FRONT FENDER QUARTER GLASS SEALANT	Not Necessary	100.00 FS	*- FS
48	1		*BODY PANEL JOINT SEALANT	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	18,182.50	9,076.20
- List Item Discount on L Items 20.00/20.00% (\$)	3,436.50	1,783.24
Total Parts (\$)	14,746.00	7,292.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,600.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	700.00
3	TO PERFORM LIGHTING & WIRING CHECK	New	150.00	30.00
4	TO APPLY ANTI-RUST & TUFF KOTE	New	180.00	50.00
5	TO REMOVE AND INSTALL FRONT QUARTER GLASS	New	100.00	0.00
6	REMOVE AND INSTALL CONDENSER AND REFILL AIRCON GAS	New	150.00	60.00
7	REMOVE AND INSTALL RADIATOR ASSY ,PERFORMED RADIATOR PRESSURE TEST	New	150.00	60.00
8	TO JACK AND REALIGN FRONT CHASSIS FRAME MEMBERS	New	350.00	0.00
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC	New	300.00	0.00
Gross Labour Cost (\$\$)			4,580.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >