



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC24120074/Uqh3e2(N)

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 03/01/2025

ATTN: MARCUS XIAO

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YR 922Z	Veh. Inspected	SMT 9474Y
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1306262-002	Excess (\$)	0.00
Assign From	MARCUS XIAO	Assign Date	05/12/2024

2. Vehicle Particulars & Condition

Make & Model	TOYOTA SIENTA HYBRID (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	NHP1707175380	Colour	BLACK
Odometer	412098 KM	Steering	AFFECTED
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65 R15	GITI	7 mm
L/H Front Tyre	185/65 R15	GITI	7 mm
R/H Rear Tyre	185/65 R15	GITI	7 mm
L/H Rear Tyre	185/65 R15	GITI	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/11/2024	Inspect Date / Time	05/12/2024 (10:09 AM)
Survey held at	T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------