ASS. REC. BY: Tayth - NEF: CS/SMR24/20075/Th43 6/6/50 10 ASSIGNMENT XD 553 R Yr Regn: 2004 08 Veh No: From: Date: Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Estimated Cost Truck / Trailer or OD / PIWS ITP RES I OD RES I EVA LINV I MV 18737 CXZ50K c.c 12 668 Make: To Inspect Vehicle No: A/C: Insured / Std / NI / NA Colour at Workshop m/s T/Radio: Insured / Std / NI / NA Sp.Reading Eng/No: Insured: TALCX 250K 6.7 000090 C/No: Policy No. Gen. Cond: 969d / Fair / Poor / Burnt Claims No. Steering: Inorder / Jammed / Leaked / Burnt or Excess: Sum Insured: Brake: Indrder / Jammed / Leaked / Burnt or (Client's Record) Modi: AT I S/Rim I STD A/Rim or F: 295/80R2215 R: ~ ~ ~ Make of Veh: Tyre Size: (Policy Condition) BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMM / OIS N/S Remark: The veh had commenced its TOYO / YOKO or repair at the time of inspection. Ball or Market Value: \$15K Rear Front mm R/Bal. Consistent?: Yes or No IDAC Accident Roort L/Bal. L/Bal. Consistent? : Yes or No GIA / PR Seen: D.O.I. 6/3/25 D.O.A. Res.: Yes or No days that thou moder Est. Repairs: 3 Val.: Yes or No Survey held at Lum Sumc Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or CA I REV I REP. I 24 HRS Vehicle: IN / OUT The U/C / Chassis frame / Body Structure affected due to collision. Person Contacted: Action / Instruction Date / Time Taufikh finalise lump sum \$1750 and 3 days (red, 6359, 78%) Days Of Repair: Date/Time, File Pass to? : Prell. Report Survey Fee: Resurvey No. of Trip: : Final Report Transportation: \_8 + RS\_\_\_SI Add Fee: : Site Insp (\$ : Interview (\$ **Photos** : Tech. Invs (\$ Others Per Formal : Weel and (\$ Lung Sten / LBJ: 17 TOTAL



## 發福摩哆車房 HUAT HOCK MOTOR WORKSHOP BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,

To display damaged part(s) during resurvey

· Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Carplate: XD553R	
Chassis No: JALCXZ50K67000090	
Accident Date: 29/11/2024	
Make & Model: ISUZU CXZ50K	

Item	F	Price	ıre: ☑/≭	Remarks
Front Bumper	\$	1,560.20-		xR
Front Bumper Bracket LH	\$	365.10		* nn
Front Bumper Bracket RH	\$	365.10		×nn
Front Bumper Top Garnish LH	\$	385.10		X nn
Front Bumper Center Garnish	\$	398.60		X nn
Front Bumper Top Garnish RH	\$	385.10		× an
Front Headlamp LH	\$	982.90		Xun
Front Step-up Board LH garniah	\$	355.60		w/
Front Side Mirror Bracket LH	\$	712.90		at
Front Side Mirror Arm LH	\$	339.20		be-
Front Side Mirror LH	\$	159.20		cut
				, 1566.90
			15)	- 133/186
All Necessary Work		Price	<b>☑/</b> ⋈	Remarks
Rewiring to facilitate repairs and check electrical				
wiring	\$	120.00		X 7 X
Respraying of undercoating	\$	180.00		X Yuh
To apply anti-rust treament on affected parts	\$	200.00		$\times$ 7
	Ś	800.00		450
including renting and repositioning of replaced parts	· *			
and replaced parts necessary for paintwork  Estimated No. of days for repairs and respray of all	\$	800.00		400 450
	Front Bumper Bracket LH Front Bumper Bracket RH Front Bumper Top Garnish LH Front Bumper Center Garnish Front Bumper Top Garnish RH Front Headlamp LH Front Step-up Board LH Front Side Mirror Bracket LH Front Side Mirror Arm LH Front Side Mirror LH  All Necessary Work Rewiring to facilitate repairs and check electrical wiring Respraying of undercoating To apply anti-rust treament on affected parts  Labour to remove and replace damaged parts,	Front Bumper Bracket LH Front Bumper Bracket RH Front Bumper Top Garnish LH Front Bumper Center Garnish Front Bumper Top Garnish RH Front Bumper Top Garnish RH Front Headlamp LH Front Step-up Board LH Front Side Mirror Bracket LH Front Side Mirror Arm LH Front Side Mirror LH  \$ Front Side Mirror LH \$ Front Side Mirror LH \$ Front Side Mirror LH \$  \$ Labour to remove and replace damaged parts, including refitting and repositioning of replaced parts \$ \$	Front Bumper \$ 1,560.20- Front Bumper Bracket LH \$ 365.10 Front Bumper Bracket RH \$ 365.10 Front Bumper Top Garnish LH \$ 385.10 Front Bumper Center Garnish \$ 398.60 Front Bumper Top Garnish RH \$ 385.10 Front Headlamp LH \$ 982.90 Front Step-up Board LH \$ 712.90 Front Side Mirror Bracket LH \$ 712.90 Front Side Mirror Arm LH \$ 339.20 Front Side Mirror LH \$ 159.20  All Necessary Work Price  Rewiring to facilitate repairs and check electrical wiring \$ 120.00 Respraying of undercoating \$ 180.00 To apply anti-rust treament on affected parts \$ 200.00  Labour to remove and replace damaged parts, including refitting and repositioning of replaced parts \$ 800.00	Front Bumper Front Bumper Bracket LH Front Bumper Bracket RH Front Bumper Top Garnish LH Front Bumper Top Garnish LH Front Bumper Top Garnish LH Front Bumper Top Garnish RH Front Bumper Top Garnish RH Front Bumper Top Garnish RH Front Step-up Board LH Front Side Mirror Bracket LH Front Side Mirror Arm LH Front Side Mirror LH  Rewiring to facilitate repairs and check electrical wiring Respraying of undercoating To apply anti-rust treament on affected parts Including refitting and repositioning of replaced parts Including refitting and repositioning of replaced parts Source Sour

Tanfilm 97495749/6256356/ wp/ 6/3/25 21540 03 days fanfilm e lhhanto.om

1331.86 2231.86 45\$1750 33 days H