

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
6 Raffles Quay, #22-00
Singapore 048580

Our File No: CS/III24120076/TNH3M4**Date:** 23/04/2025**REFERENCE****Insured/Claimant:** COMFORTDELGRO BUS PTE LTD**Policy No:** D24MFL008848**Date of Loss:** 29/11/2024**Nature of Claim:** OD**Claim No:** MFL2024D0014311**DESCRIPTION & IDENTIFICATION OF VEHICLE****Reg No:** PC6372G**Make & Model:** VOLVO B7R, 7.1 (A)**Engine No:** D7E12041692**Reg. Date:** 16/11/2017 (Man. Year: 2017)**Chassis No:** YV3R6R624HA186894**Colour:** Blue**Odometer:** 293184 km**Engine Capacity:** 7146 cc**Market Value/New Car Price:** S\$55,000.00**Sum Insured (S\$):** **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY****General Condition:** Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes **Engine Modification:**No **Pre-accident Condition:****CONDITION OF TYRES****Front Tyre Size:** 295/80R22.5**Rear Tyre Size:** 295/80R22.5 (D)**Front Left Side:** DURATURN 8 mm**Rear Left Side:** DURATURN 8/8 mm**Front Right Side:** DURATURN 8 mm**Rear Right Side:** DURATURN 8/8 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	37,586.00	20,360.20	17,225.80	45.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,830.00	2,030.00	800.00	28.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	40,416.00	22,390.20	18,025.80	44.60
Approved Total (Overridden) (S\$)		17,900.00		
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	38,916.00	16,400.00	22,516.00	57.86
+ GST 9.00/9.00% (S\$)	3,502.44	1,476.00	2,026.44	57.86
Nett Amount (S\$)	42,418.44	17,876.00	24,542.44	57.86

INSPECTION**Date of Assignment:** 05/12/2024**Date Inspected:** 06/12/2024 **Inspected At:**CONNECT3 (WOODLANDS) (HQ)
566 WOODLANDS ROAD (MANDAI ESTATE)
SINGAPORE 728697**Estimated Period of Repair:** 8.0 days**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 23 Apr 2025)	
Parts:	N/A	VOLVO B7R 7.1 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC6372G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	1,850.00 F	*1,850.00 FL
2	1		*REAR BUMPER INNER STRUCTURE	Bent	780.00 F	*780.00 FL
3	2		*REAR BUMPER LH & RH BRACKET	Repair	750.00 F	*- FL
4	1		*REAR TAILGATE OUTER PANEL	Bent	4,200.00 F	*4,200.00 FL
5	2		*REAR TAILGATE GAS SPRING	Bent	370.00 F	*370.00 FL
6	1		*REAR TAILGATE HINGE LH	Bent	355.00 F	*355.00 FL
7	1		*REAR RH TAILLAMP	Cut	1,850.00 F	*1,850.00 FL
8	1		*INTERCOOLER	Not Necessary	3,977.00 F	*- FL
9	1		*RADIATOR ASSY	Not Necessary	7,856.00 F	*- FL
10	1		*RADIATOR BASE	Not Necessary	720.00 F	*- FL
11	6		*RADIATOR BASE BRACKET	Not Necessary	1,062.00 F	*- FL
12	1		*RADIATOR CAP	Not Necessary	83.00 F	*- FL
13	1		*VOLVO EMBLEM	Necessary	109.00 F	*109.00 FL
14	1		*B7R EMBLEM	Necessary	89.00 F	*89.00 FL
15	1		*60KM/H STICKER	Necessary	15.00 F	*15.00 FL
16	1		*MAIN PULLEY	Broken	6,800.00 F	*6,800.00 FL
17	1		*MAIN PULLEY FAN BELT	Torn	980.00 F	*980.00 FL
18	1		*MAIN PULLEY BRACKET	Not Necessary	520.00 F	*- FL
19	1		*TENSIONER PULLEY	Bent	2,750.00 F	*2,750.00 FL
20	2		*TAILGATE LH & RH SIDE LOCK	Bent	1,100.00 F	*1,100.00 FL
21	1		*SPARE TANK HOSE	Broken	285.00 F	*285.00 FL
22	1		*TAILGATE CENTER OUTER LOCK	Bent	560.00 F	*560.00 FL
23	1		*RADIATOR HOSE	Bent	485.00 F	*485.00 FL
24	1		*REAR NUMBER PLATE	Bent	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	37,586.00	22,618.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	2,257.80
Total Parts (\$)	37,586.00	20,360.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING	New	30.00	30.00
2	LABOUR CHARGES	New	1,800.00	1,200.00
3	SPRAY PAINTING	New	1,000.00	800.00
Gross Labour Cost (\$\$)			2,830.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >