

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24120080/UQH3E2**Date:** 19/06/2025REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SLF355C **Insured Vehicle No :** SND1314B

Date of Loss: 04/12/2024 Nature of Claim: TP Claim No: DMPC2401688H/02/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLF355C**

Make & Model: MAZDA 3, 1.5 HATCHBACK L SP.6EAT (A) Engine No: P520368751

Reg. Date: 11/08/2016 (Man. Year: 2016) Chassis No: JM6BM44A8G0343022

Colour: Red Odometer: 156844 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18

Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,130.24	1,121.84	1,008.40	47.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	550.00	1,080.00	66.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,760.24	1,671.84	2,088.40	55.54
Approved Total (Overridden) (S\$)		1,300.00		
Nett Amount (S\$)	3,760.24	1,300.00	2,460.24	65.43

INSPECTION

Date of Assignment: 05/12/2024

Date Inspected: 06/12/2024 Inspected At: Zoom Autowerks Pte Ltd (HQ)
15 Kaki Bukit Road 4, #01-53
Singapore 417808

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jun 2025)
Parts:	144	MAZDA 3 1.5 HATCHBACK L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF355C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed / Dented	1,102.30 FL	*1,102.30 FL
2	1		*REAR BUMPER BEAM	Repair	766.50 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER O/S	Not Necessary	112.00 FL	*- FL
4	1		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
5	1		*SET REAR BUMPER REVERSE SENSOR	Malfunction	250.00 FL	*250.00 FL
6	1		*REAR END PANEL	Repair	382.00 FL	*- FL
					Sub Total (S\$)	2,662.80 1,402.30
					- List Item Discount on L Items 20.00/20.00% (S\$)	532.56 280.46
					Total Parts (S\$)	2,130.24 1,121.84

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	100.00	30.00
3	TO SPRAY RUST PROOFING	New	100.00	0.00
4	TO TRANSFER SEAT CUSHION UPHOLSTERY	New	100.00	0.00
5	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	680.00	200.00
6	TO PUTTY & SPRAY PAINTING	New	600.00	300.00
Gross Labour Cost (\$)			1,630.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >