

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI24120084/EVH3E2
Date: 16/12/2024**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MS008163
Claimant Vehicle No :	SHA4498X	Insured Vehicle No :	GBB1238R
Date of Loss:	05/12/2024	Nature of Claim:	TP
		Claim No:	M2407147

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA4498X		
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT TAXI (A)	Engine No:	2ZRR971263
Reg. Date:	23/12/2016 (Man. Year: 2016)	Chassis No:	JTDKB3FUX03539075
Colour:	Blue	Odometer:	853729 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,464.87	4,632.54	4,832.33	51.06
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	2,145.00	1,835.00	310.00	14.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,621.87	6,479.54	5,142.33	44.25
Approved Total (Overridden) (S\$)		5,150.00		
(S\$)	11,621.87	5,150.00	6,471.87	55.69
+ GST 9.00/9.00% (S\$)	1,045.97	463.50	582.47	55.69
Nett Amount (S\$)	12,667.84	5,613.50	7,054.34	55.69

INSPECTION

Date of Assignment:	06/12/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	06/12/2024	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	4.0 days		

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Dec 2024)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA4498X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Broken	586.18 FL	*586.18 FL
2	1		*FRT BUMPER UPR BRKT RH	Not Necessary	82.30 FL	*- FL
3	1		*FRT BUMPER RETAINER RH	Broken	77.00 FL	*77.00 FL
4	10		*FRT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
5	1		*FRT FENDER RH	Dented	1,111.93 FL	*1,111.93 FL
6	1		*FRT FENDER SHIELD RH	Crushed	198.50 FL	*198.50 FL
7	1		*FRT FENDER (HYBRID) RH	Necessary	86.50 FL	*86.50 FL
8	1		*FRT WHEEL RIM RH	Repair	1,570.55 FL	*- FL
9	1		*FRT BUMPER UPPER GRILLE	Not Necessary	301.90 FL	*- FL
10	1		*FRT BUMPER LOWER GRILLE	Crushed	193.18 FL	*193.18 FL
11	1		*BONNET	Repair	1,117.93 FL	*- FL
12	1		*HEADLAMP RH	Broken	2,637.60 FL	*2,637.60 FL
13	1		*DAYLIGHT RH	Not Necessary	920.00 FL	*- FL
14	1		*HEADLAMP TOP PANEL	Repair	364.98 FL	*- FL
15	1		*HEADLAMP PANEL RH	Repair	240.10 FL	*- FL
16	1		*HEADLAMP LOWER PANEL	Not Necessary	320.65 FL	*- FL
17	1		*RADIATOR GRILLE	Crushed	438.00 FL	*438.00 FL
18	1		*RADIATOR GRILLE EMBLEM	Necessary	88.00 FL	*88.00 FL
19	1		*FRT BUMPER SPONGE	Broken	78.80 FL	*78.80 FL
20	1		*FRT BUMPER REINFORCEMENT	Not Necessary	812.89 FL	*- FL
21	1		*WIPER WASHER TANK	Crushed	486.70 FL	*486.70 FL
22	1		*WIPER WASHER TANK MOTOR	Not Necessary	242.70 FL	*- FL
23	1		*FRT NO.PLATE WITH TRIM COVER	Crushed	55.00 F	*55.00 F
24	1		*FRT NO.PLATE BASE GARNISH	Crushed	99.00 FL	*99.00 FL
25	1		*ENGINE UNDER COVER	Not Necessary	288.30 FL	*- FL
26	1		*FRT SIDE UNDER COVER RH	Not Necessary	180.80 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	12,601.49	6,158.39
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,136.62	1,525.85
Total Parts (\$\$)	9,464.87	4,632.54

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	760.00
2	SPRAY PAINTING	New	900.00	840.00
3	CHECK LIGHTINGS	New	40.00	30.00
4	TUFF KOTE	New	60.00	20.00
5	R/I RADIATOR & CONDENSER ETC	New	120.00	0.00
6	WHEEL ALIGNMENT	New	120.00	80.00
7	TOWING FEE - chit attached	New	105.00	105.00
Gross Labour Cost (\$)			2,145.00	1,835.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >