

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24120088/AMA3Q2**Date:** 18/06/2025REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100507765
Claimant Vehicle No :	YP8721U	Insured Vehicle No :	SLM9895P
Date of Loss:	28/11/2024	Nature of Claim:	TP
		Claim No:	7710617229SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP8721U		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER4SDEN (CBU) (M)	Engine No:	4P10D20456
Reg. Date:	13/06/2018 (Man. Year: 2018)	Chassis No:	FEB21EA25163
Colour:	White	Odometer:	342993 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,248.02	5,110.35	14,137.67	73.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,820.00	1,520.00	2,300.00	60.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,068.02	6,630.35	16,437.67	71.26
Approved Total (Overridden) (S\$)		5,300.00		
Nett Amount (S\$)	23,068.02	5,300.00	17,768.02	77.02
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
Nett Liability (S\$)		5,900.00		
Global Sum Settlement (S\$)		5,900.00		

INSPECTION

Date of Assignment:	28/11/2024	
Date Inspected:	28/11/2024	Inspected At: Kt Motorwerk (HQ) Blk 3012 Bedok Industrial Park E, #01-2020 Singapore 489978
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Dented	2,601.65 FL	*1,860.00 FL
2	1		*FRONT DOOR DUONIC STICKER	Necessary	74.43 FL	*74.43 FL
3	1		*FRONT DOOR OUTER KEY LOCK RH	Not Necessary	187.44 FL	*- FL
4	1		*FRONT DOOR OUTER HANDLE RH	Not Necessary	248.61 FL	*- FL
5	1		*FRONT DOOR OUTER STRIP RH	Not Necessary	184.62 FL	*- FL
6	1		*FRONT DOOR ACED GARNISH RH	Cut	498.14 FL	*425.00 FL
7	1		*FRONT DOOR ACED GARNISH RUBBER RH	Not Necessary	87.55 FL	*- FL
8	1		*FRONT DOOR WEATHERSTIRP RH	Not Necessary	424.82 FL	*- FL
9	1		*FRONT DOOR INNER LOCK RH	Not Necessary	744.63 FL	*- FL
10	1		*FRONT DOOR LOCK CATCH RH	Not Necessary	55.26 FL	*- FL
11	1		*FRONT DOOR FRAME WEATHERSTRIP RH	Not Necessary	329.54 FL	*- FL
12	1		*FRONT DOOR LIGHT SWITCH RH	Not Necessary	199.27 FL	*- FL
13	1		*FRONT WHEEL BACK MUDGUARD RH	Cut	594.54 FL	*468.00 FL
14	1		*FRONT WHEEL HOUSE ARCED PANEL RH	Not Necessary	396.81 FL	*- FL
15	1		*SIDE GATE RH	Repair	3,983.25 FL	*- FL
16	1		*SIDE GATE STOPPER RH	Missing	68.41 FL	*68.41 FL
17	7		*SIDE GATE HINGE RH	Not Necessary	1,264.34 FL	*- FL
18	1		*SIDE GATE FRONT LOCK RH	Not Necessary	390.41 FL	*- FL
19	1		*CABIN BACK CORNER PANEL RH	Not Necessary	1,242.84 FL	*- FL
20	1		*CABIN BACK CORNER BOTTOM PANEL RH	Not Necessary	128.40 FL	*- FL
21	1		*CARGO BED SIDE BEAM RH	Not Necessary	2,540.00 FL	*- FL
22	1		*SET FRONT DOOR INNER TRIM CLIP RH	Not Necessary	60.00 FS	*- FS
23	1		*SET FRONT DOOR ARCED GARNISH CLIP LH	Necessary	50.00 FS	*30.00 FS
24	1		*SET FRONT DOOR INNER TRIM CLIP LH	Not Necessary	50.00 FS	*- FS
25	1		*SET FRONT DOOR COMPANY STICKER (SPECIAL TYRE)	Necessary	650.00 FS	*200.00 FS
26	1		*FRONT DOOR BIZSAFE STICKER (SPECIAL TYPE)	Not Necessary	120.00 FS	*- FS
27	1		*FRONT WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
28	1		*SET CABIN INN TRIM GARNISH CLIP	Not Necessary	60.00 FS	*- FS
29	1		*CABIN CANOPY MAT RH	Torn	1,200.00 FS	*800.00 FS
30	1		*CABIN CANOPY MAT HOLDER RH	Not Necessary	450.00 FS	*- FS
31	1		*CABIN BACK CORNER PANEL WARNING STICKER (SPECIAL TYRE)	Not Necessary	80.00 FS	*- FS
32	1		*SET SIDE GATE COMPANY STICKER (SPECIAL TYPE)	Necessary	850.00 FS	*550.00 FS
33	1		*SIDE SAFETY BAR (SEPCIAL TYPE)	Bent	1,200.00 FS	*450.00 FS
34	1		*FRONT BUMPER	Cut	456.30 FL	*456.30 FL
35	1		*FRONT DOOR STEP GARNISH	Cut	466.70 FL	*310.00 FL
36	1		*FRONT DOOR BLUETEC STICKER	Necessary	60.00 FL	*60.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
37	1		*FRONT SIGNAL LAMP RH	Not Necessary	486.70 FL	*- FL
38	1		*FRONT HEADLAMP RH	Not Necessary	522.10 FL	*- FL
39	1		*FRONT TYRE RH	Not Necessary	250.00 FL	*- FL
40	1		*FRONT SPARE TANK	Not Necessary	325.60 FL	*- FL
41	1		*REAR WHEEL MUDGUARD	Deformed	385.00 FL	*385.00 FL
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	24,047.36
					- List Item Discount on L Items 25.00/25.00% (\$\$)	4,799.34
					Total Parts (\$\$)	19,248.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,WELD ,CUT ADJUST ,KNOCK	New	1,600.00	700.00
2	TO PUTTY ,SRPAY PAINT POLISH WAX	New	1,600.00	700.00
3	TO SPRAY TUFF COAT	New	250.00	40.00
4	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	150.00	0.00
6	TRANFER FRONT DOOR MECHANISM	New	80.00	40.00
7	REMOVE AND REINSTALL WINDOW GLASS	New	60.00	40.00
Gross Labour Cost (\$\$)			3,820.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >