

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS24120093/KNH3E2

Date: 24/03/2025

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SNR6832R	Insured Vehicle No :	SFB1819S
Date of Loss:	28/11/2024	Nature of Claim:	TP
		Claim No:	DMPC2401647H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNR6832R		
Make & Model:	HYUNDAI SX2 KONA, 1.6 GDI HEV (A)	Engine No:	G4LLRU430133
Reg. Date:	28/06/2024 (Man. Year: 2024)	Chassis No:	KMHHB811VRU071103
Colour:	White	Odometer:	45856 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,694.96	10,252.31	8,442.65	45.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,900.00	2,140.00	2,760.00	56.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	23,594.96	12,392.31	11,202.65	47.48
+ GST 9.00/9.00% (\$\$)	2,123.55	1,115.31	1,008.24	47.48
Nett Amount (\$\$)	25,718.51	13,507.62	12,210.89	47.48

INSPECTION

Date of Assignment:	06/12/2024	
Date Inspected:	09/12/2024	Inspected At: Lim Tan Motor Pte Ltd (HQ) Blk 176 Sin Ming Drive #03-09/10, Sin Ming Auto Care Singapore 575721
Estimated Period of Repair:	7.0 days	

Adjuster: KENNETH KONG

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Mar 2025)
Parts:	192	HYUNDAI SX2 KONA 1.6 GDI HEV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNR6832R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,015.00 FL	*1,015.00 FL
2	1		*REAR BUMPER LOWER DIFFUSER	Mtg Cracked	856.70 FL	*510.39 FL
3	1		*REAR BUMPER RH LAMP	Serviceable	953.00 FL	*- FL
4	1		*REAR BUMPER RH RETAINER	Cracked	32.00 FL	*32.00 FL
5	1		*REAR BUMPER RH COVER	Cracked	201.00 FL	*201.00 FL
6	1		*REAR RH FENDER UNDERSHIELD	Distorted	275.00 FL	*275.00 FL
7	1		*REAR RH FENDER ARCH GARNISH	Serviceable	473.00 FL	*- FL
8	1		*REAR RH RADAR	Serviceable	1,568.00 FL	*- FL
9	1		*REAR RH DOOR	Bent	2,063.00 FL	*2,063.00 FL
10	1		*REAR RH DOOR FRAME TAPE	Necessary	55.00 FL	*55.00 FL
11	1		*REAR RH DOOR PROTECTOR	Cut	485.00 FL	*485.00 FL
12	1		*REAR RH DOOR REGULATOR	Serviceable	277.00 FL	*- FL
13	1		*REAR RH DOOR POWER WINDOW MOTOR	Serviceable	370.00 FL	*- FL
14	1		*REAR RH DOOR CHANNEL	Serviceable	241.00 FL	*- FL
15	1		*REAR RH DOOR RUBBER	Serviceable	171.00 FL	*- FL
16	1		*REAR RH DOOR CHECK	Serviceable	50.00 FL	*- FL
17	2		*REAR RH DOOR HINGES	Bent	240.00 FL	*240.00 FL
18	1		*FRONT RH DOOR	Bent	1,789.00 FL	*1,789.00 FL
19	1		*FRONT RH DOOR LOCK	Repair	398.00 FL	*- FL
20	1		*FRONT RH DOOR FRAME TAPE	Necessary	85.00 FL	*85.00 FL
21	1		*FRONT RH RUBBER	Serviceable	153.00 FL	*- FL
22	1		*FRONT RH DOOR REGULATOR	Serviceable	283.00 FL	*- FL
23	1		*FRONT RH DOOR POWER WINDOW MOTOR	Serviceable	370.00 FL	*- FL
24	1		*FRONT RH DOOR CHANNEL	Serviceable	241.00 FL	*- FL
25	1		*RH SIDE SKIRT	Serviceable	600.00 FL	*- FL
26	1		*FRONT RH FENDER ARCH GARNISH	Cut	473.00 FL	*473.00 FL
27	1		*FRONT RH FENDER UNDER-SHIELD	Serviceable	163.00 FL	*- FL
28	1		*FRONT BUMPER	Repair	726.00 FL	*- FL
29	1		*FRONT BUMPER LOWER	Cut	1,100.00 FL	*1,100.00 FL
30	1		*FRONT BUMPER RH LAMP	Cut	2,216.00 FL	*2,216.00 FL
31	1		*FRONT BUMPER RH RETAINER	Distorted	25.00 FL	*25.00 FL
32	2		*RIM	Dented	1,766.00 FL	*1,766.00 FL
33	1		*FRONT RH KNUCKLE ARM	Serviceable	518.00 FL	*- FL
34	1		*FRONT RH LOWER ARM	Serviceable	808.00 FL	*- FL
35	1		*FRONT RH LOWER ARM	Serviceable	107.00 FL	*- FL
36	1		*FRONT RH SHOCK ABSORBER	Serviceable	490.00 FL	*- FL
37	1		*FRONT STABILIZER BAR	Serviceable	383.00 FL	*- FL
38	1		*FRONT STEERING LINK	Serviceable	143.00 FL	*- FL
39	1		*FRONT WHEEL BEARING HUB	Serviceable	721.00 FL	*- FL
40	1		*FRONT RH DOOR PROTECTOR	Dented / Cut	485.00 FL	*485.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$) 23,368.70 12,815.39

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 20.00/20.00% (S\$)					4,673.74	2,563.08
Total Parts (S\$)					18,694.96	10,252.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY AND SPRAY PAINT	New	1,800.00	1,000.00
2	TOWING	New	100.00	60.00
3	TO TRANSFER DOOR FITTING	New	100.00	100.00
4	TO REPLACE FRONT UNDER CARRIAGE	New	350.00	0.00
5	TO CHECK WHEEL ALIGNMENT	New	800.00	120.00
6	TO ANTI RUST	New	150.00	60.00
7	LABOUR CHARGES	New	1,600.00	800.00
Gross Labour Cost (\$\$)			4,900.00	2,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >