



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SCA 1001A

Qty	Description of Parts	Condition	Recommended (\$)
	<u>REPLACEMENT OF PARTS</u>		
1	REAR TAILLAMP RH	BROKEN	1,028.00
1	REAR TAILLAMP SEAL RH	NECESSARY	82.00
1	REAR BUMPER ASSY	DENTED/BUCKLED	2,150.00
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	-
1	REAR FENDER RH	BENT	3,926.00
1	REAR FENDER INNER GARNISH RH	DISTORTED	418.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	-
1	REAR END PANEL TOP GARNISH	DISTORTED	141.00
	LESS 10% DISCOUNT		-774.50
			6,970.50
	<u>LABOUR</u>		
	LABOUR FOR PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT AND REAR END PANEL.		700.00
	SPRAY PAINT.		500.00
	R/R REAR GARNISHES & ETC.		100.00
	CHECK WIRING.		20.00
	TUFF COAT.		30.00
			1,350.00
	GRAND TOTAL		8,320.50

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	6,650.00
---	-----------------

Report Ref No. CS3/SPF24120094/Knh3m4(N)

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$7,000

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.