

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	AUTOMOTIVE EN	GRG. & MGT. DIVISION (TP)	F	Ref:	CS3/SPF24120094/Knh3m4(N)	
	FORCE) POLICE L	S SECTION (SPORE POLICE OGISTICS BASE (PLB) 1 SINGAPORE 438675	Г	Date:	07/02/2025	
	ATTN: LAI PENGC	HONG	C	Code:	SPF	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	YQ 2445B	Veh. Inspected		SCA 1001A	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	ACS/105/009/2024/062(LK)	Excess (\$)		0.00	
	Assign From	LAI PENGCHONG	Assign Date		06/12/2024	
2. Vehicle Particulars & Condition						
	Make & Model	MERCEDES BENZ 300SL-24 AT	c.c		2960	
	Engine No.	HIDDEN	Year of Reg.		1992	
	Chassis No.	WDB1290612F050938	Colour		METALLIC RED	
	Odometer	125312 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/55R16	MICHELIN		8 mm	
	L/H Front Tyre	225/55R16	MICHELIN		8 mm	
	R/H Rear Tyre	225/55R16	MICHELIN		7 mm	
	L/H Rear Tyre	225/55R16	MICHELIN		7 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	29/11/2024	Inspect Date / Ti	ime	09/12/2024 ( 05:10 PM )	
	Survey held at	THIAM HENG HUAT PTE LTD				
		176 SIN MING DRIVE #05-14 SINGAPORE 575721				
5a.	a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					
5b.	b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					