

CS/MSG 24120095/DVH³


ASSIGNMENT

COB 11 Sept 2032
12 Sept 2024

From: _____ Date: _____
 Estimated Cost: _____
 OB / TP / WS / TP RES / OD RES / EVA / NV / MV
 To inspect Vehicle No: _____
 at Workshop n/s _____
 of _____
 Insured: SNJ 4636X
 Policy No: 1003628980
 Claims No: 383808
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 DAC Accident Report: _____ Consistent?: Yes or No
 GA / PR Seen: _____ Consistent?: Yes or No
 Est. Repair: 6 days Res: Yes or No
 Lump Sum: 91P % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: STD 3050U
 Yr Regn: 12 Sept 2024
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Hyundai Kona CC 1580
 Colour: Blue A/C: Insured / Std / Nil / NA
 Sp. Reading: 36165 T/Radio: Insured / Std / Nil / NA
 Eng No: G4LLRU450026
 C/No: KMH811V SU086664
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / SRim / STD A/Rim or
 Tyre Size: F: 205/65 R16
 R: 11
 BS / DUN / EXIOVA / GY / FS / LZA / NIC / OHTSU / PR / SUMI /
 TOYO / YOKO or Kumho
 Front
 R/Bal: 5 mm R/Bal: 5 mm
 L/Bal: 5 mm L/Bal: 5 mm
 D.O.A: 06/12/2024 D.O.I: 09/12/2024
 Survey held at: Rightmost Lorry
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Roofing or
 Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time	Action/Instruction
	MSG SNJ 4636X
18/3/25	for to seek mandate PIP 8,162.36 & 8% J.R.

Days of Repair: 6
 Resurvey No. of Trip: _____

Days of Repair: 6
 Resurvey No. of Trip: _____

Report Format: _____
 Lump Sum / L.R. (\$) _____

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:	
Transporter:	
S-RS	
Photo	
Other	
TOTAL	

REPAIR ESTIMATE

DATE: 6-Dec-24

MODEL: HYUNDAI KONA

VEHICLE NO.: SHD 3050 U

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR BUMPER <i>Demol</i>	1	\$ 1,015.00	\$ 1,015.00
BEAM-REAR BUMPER <i>Demol</i>	1	\$ 582.00	\$ 582.00
STAY-RR BUMPER,(LH/RH) <i>hml</i>	2	\$ 55.00	\$ 110.00
BRACKET ASSY-RR BUMPER LWR,(LH/RH) <i>hml</i>	2	\$ 32.00	\$ 64.00
CAP-RR HOOK <i>src</i>	1	\$ 11.00	\$ 11.00
DIFFUSER ASSY-RR BUMPER <i>Demol</i>	1	\$ 856.70	\$ 856.70
PARKING SENSOR <i>src</i>	2	\$ 262.00	\$ 524.00
PARKING SENSOR WIRE <i>hml</i>	1	585.35	\$ 585.35
REAR END PANEL <i>Demol</i>	1	\$ 729.00	\$ 729.00
REAR END PANEL GARNISH <i>broken</i>	1	\$ 190.00	\$ 190.00
PANEL ASSY-TAIL GATE <i>Demol</i>	1	\$ 2,164.00	\$ 2,164.00
HINGE ASSY-TAIL GATE (LH/RH) <i>hml</i>	2	\$ 28.00	\$ 56.00
TRIM ASSY-TAIL GATE LWR <i>defunct</i>	1	\$ 378.00	\$ 378.00
TRIM ASSY-TAIL GATE UPR <i>hml</i>	1	\$ 63.00	\$ 63.00
TRIM ASSY-TAIL GATE FRAME SIDE (LH/RH) <i>hml</i>	2	\$ 39.00	\$ 78.00
W/STRIP-TAIL GATE OPNG <i>defunct</i>	1	\$ 137.00	\$ 137.00
LATCH ASSY-TAIL GATE <i>bst / Demol</i>	1	\$ 278.00	\$ 278.00
STRIKER ASSY-T/GATE <i>hml</i>	1	\$ 25.00	\$ 25.00
HANDLE ASSY-TAIL GATE O/S <i>hml</i>	1	\$ 125.00	\$ 125.00
LIFTER ASSY-TAIL GATE,(LH/RH) <i>hml</i>	2	\$ 111.00	\$ 222.00
BOOT TOP COVER CTR <i>hml</i>	1	\$ 455.00	\$ 455.00
BOOT EMBLEM-SYMBOL MARK <i>bst</i>	1	\$ 72.00	\$ 72.00
EMBLEM-KONA <i>bst</i>	1	\$ 97.00	\$ 97.00
EMBLEM-HYBRID <i>hml</i>	1	\$ 47.00	\$ 47.00
SPOILER-RR <i>hml</i>	1	\$ 1,347.00	\$ 1,347.00
GARNISH ASSY-TAIL GATE <i>hml</i>	1	\$ 375.00	\$ 375.00
REAR NUMBER PLATE LAMP <i>broken</i>	2	\$ 231.00	\$ 462.00
3RD BRAKE LAMP ASSY-CENTER POSITION <i>broken</i>	1	\$ 6,604.00	\$ 6,604.00
LAMP ASSY-REAR COMB OUTSIDE,LH <i>hml</i>	2	\$ 717.00	\$ 1,434.00
LAMP ASSY-REAR COMB LH,LWR <i>hml</i>	2	\$ 953.00	\$ 1,906.00
LAMP ASSY-REAR FOG <i>ext</i>	1	\$ 163.00	\$ 163.00
3RD BRAKE LAMP ASSY-HMS <i>hml</i>	1	\$ 220.00	\$ 220.00
UNIT ASSY-REAR VIEW CAMERA <i>src</i>	1	\$ 1,088.00	\$ 1,088.00
REAR MUFFLER <i>hml</i>	1	\$ 1,341.00	\$ 1,341.00
REAR MUFFLER HEAT SHIELD <i>hml</i>	1	\$ 235.00	\$ 235.00
REAR MUFFLER MOUNTING <i>hml</i>	2	\$ 22.00	\$ 44.00
SUB TOTAL			\$ 24,083.05

$\frac{1}{x} \times x = 1$

1306.00

$$\begin{array}{r} 8476.70 \\ 6.781.36 \\ \hline \end{array}$$

LESS 20%				\$	4,816.61
DISCOUNTED TOTAL				\$	19,266.44
REAR NUMNER PLATE <i>broken</i>	SN	1	\$	45.00	\$ 45.00
COMFORT LOGO <i>hec</i>	SN	1	\$	80.00	\$ 80.00
REAR WINDSCREEN SEALANT <i>hec</i>	SN	1	\$	46.00	\$ 46.00
SUB TOTAL				\$	171.00
Labour Charge					
Panel Beating		1	\$2,000.00	\$	2,000.00
Spray Painting Charge		1	\$1,600.00	\$	1,600.00
Wiring Charge		1	\$100.00	\$	100.00
Tuff Kote		1	\$100.00	\$	100.00
Towing Charge		1	\$80.00	\$	80.00
Remove/Refix Cushion & Upholstery Rear		1	\$150.00	\$	150.00
Remove/Refix Rear Windscreen Glass		1	\$120.00	\$	120.00
Diagnostic & Resetting To Erase Fault Code		1	\$550.00	\$	550.00
TOTAL LABOUR				\$	4,700.00
ESTIMATE TOTAL				\$	24,137.44
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

✓
✓
✓

171.00

600/-
400/-
30/-
20/-
44
80/-
80/-
44

1210.00

09/12/2024 e 1300m

P/P 8,162-36

N/A Actual

Part by Part

5 days

[Signature]

Photo after

LKK Auto

ign

with damage
Part.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: