

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24070007/APA3Q2**Date:** 18/11/2024REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070143849
Claimant Vehicle No :	SLQ5716D	Insured Vehicle No :	SKW6199U
Date of Loss:	30/06/2024	Nature of Claim:	TP
		Claim No:	2596183715SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ5716D		
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Engine No:	CVN038995
Reg. Date:	14/07/2017 (Man. Year: 2017)	Chassis No:	WAUZZZF44HA164740
Colour:	Blue	Odometer:	175842 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,576.00	10,641.28	7,934.72	42.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,902.00	3,102.00	1,800.00	36.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,478.00	13,743.28	9,734.72	41.46
+ GST 9.00/9.00% (S\$)	2,113.02	1,236.90	876.12	41.46
Nett Amount (S\$)	25,591.02	14,980.18	10,610.84	41.46
+ Car Rental (4.0 x S\$100.00/day + 9.00% GST) (S\$)		436.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		15,418.36		

INSPECTION

Date of Assignment:	01/07/2024		
Date Inspected:	05/07/2024	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,670.00 FS	*2,136.00 FS
2	1		*FRONT BUMPER FIXING PARTS (NPA)	Not Necessary	0.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	90.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	286.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE -RH	Not Necessary	8.00 FS	*- FS
6	1		*RADIATOR GRILLE-RH	Not Necessary	1,371.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE -RH	Not Necessary	169.00 FS	*- FS
8	1		*FRONT BUMPER GUIDE SECTION -RH	Broken	46.00 FS	*36.32 FS
9	1		*FRONT BUMPER BRACKET -RH	Not Necessary	173.00 FS	*- FS
10	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	1,033.00 FS	*- FS
11	2		*FRT LOCK CARRIER TOP SUPPORT BRACKET -LH/RH	Not Necessary	74.00 FS	*- FS
12	1		*OUTSIDE TEMP SENSOR BRACKET	Not Necessary	30.00 FS	*- FS
13	1		*LED HEADLIGHT -RH	Cut	9,325.00 FS	*7,460.00 FS
14	3		*LED HEADLIGHT SPACER -RH	Not Necessary	150.00 FS	*- FS
15	1		*LIFT CYLINDER -RH	Not Necessary	252.00 FS	*- FS
16	1		*LIFT CYLINDER BRACKET-RH	Not Necessary	8.00 FS	*- FS
17	1		*LIFT CYLINDER HOSE	Not Necessary	118.00 FS	*- FS
18	1		*FRONT FENDER -RH	Dented	918.00 FS	*734.40 FS
19	1		*FRONT FENDER ATTACHMENT PARTS RH	Not Necessary	241.00 FS	*- FS
20	1		*FRONT FENDER BRACKET -RH	Not Necessary	45.00 FS	*- FS
21	1		*FRONT FENDER BRACKET -RH	Not Necessary	72.00 FS	*- FS
22	1		*FRONT FENDER RIVET -RH (6 PCS)	Necessary	26.00 FS	*20.16 FS
23	1		*FRONT FENDER BRACKET -RH	Not Necessary	67.00 FS	*- FS
24	1		*FRONT FENDER BRACKET -RH	Not Necessary	42.00 FS	*- FS
25	1		*FRONT FENDER BRACE -RH	Not Necessary	177.00 FS	*- FS
26	1		*FRONT WHEEL HOUSING LINER -RH	Not Necessary	294.00 FS	*- FS
27	1		*FRONT WHEEL HOUSING LINER ATTACHMENT -RH (NPA)	Not Necessary	0.00 FS	*- FS
28	1		*FRONT WHEEL SPOILER	Broken	92.00 FS	*73.12 FS
29	1		*FRONT FENDER COVER -RH	Not Necessary	76.00 FS	*- FS
30	1		*FRONT FENDER LEDGE COVER -RH LONG	Broken	39.00 FS	*31.04 FS
31	1		*FRONT FENDER LEDGE COVER -RH SHORT	Broken	29.00 FS	*22.48 FS
32	1		*SUNDRIES	Necessary	500.00 FS	*4.64 FS
33	1		*SECURING ELEMENT FOR WHEEL HOUSING LINER RHS	Broken	65.00 FS	*51.36 FS
34	1		*RHS FRONT FENDER CLOSING ELEMENT	Broken	90.00 FS	*71.76 FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **18,576.00** **10,641.28**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT ,HORNS OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT AND CONTROL UNIT AND POWER MODULE	New	350.00	350.00
3	TO DISMANTLE AND RENEW FRONT BUMPER ,RHS FRONT FENDER AND RHS HEADLIGHT RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	1,800.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (\$\$)			4,902.00	3,102.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >