

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/AIG24120099/EPA3Q2**Date:** 28/03/2025**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800092379  
**Claimant Vehicle No :** SNF6274P **Insured Vehicle No :** SDD6996T  
 Date of Loss: 06/12/2024 Nature of Claim: TP Claim No: 5792095027SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SNF6274P**  
 Make & Model: HYUNDAI CN7 AVANTE, 1.6 DOHC CVT S (A) Engine No: G4FMNU179897  
 Reg. Date: 13/06/2022 (Man. Year: 2022) Chassis No: KMHLN41ETNU322825  
 Colour: White Odometer: 81949 km  
 Engine Capacity: 1598 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm  
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                           | 14,394.64         | 5,390.24          | 9,004.40          | 62.55         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour                                          | 6,210.00          | 1,790.00          | 4,420.00          | 71.18         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing                                          | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>20,604.64</b>  | <b>7,180.24</b>   | <b>13,424.40</b>  | <b>65.15</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>5,750.00</b>   |                   |               |
| <b>(S\$)</b>                                    | 20,604.64         | 5,750.00          | 14,854.64         | 72.09         |
| <b>+ GST 9.00/9.00% (S\$)</b>                   | 1,854.42          | 517.50            | 1,336.92          | 72.09         |
| <b>Nett Amount (S\$)</b>                        | <b>22,459.06</b>  | <b>6,267.50</b>   | <b>16,191.56</b>  | <b>72.09</b>  |
| <b>+ Loss of Use (8.0 x S\$60.00/day) (S\$)</b> |                   | 480.00            |                   |               |
| <b>(S\$)</b>                                    |                   | 6,747.50          |                   |               |
| <b>Liabe Amount (90.00%) (S\$)</b>              |                   | <b>6,072.75</b>   |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 27.25             |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>6,100.00</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>              |                   | <b>6,100.00</b>   |                   |               |

**INSPECTION**

Date of Assignment: 09/12/2024  
 Date Inspected: 09/12/2024 Inspected At: HD Perfect Autowork Pte Ltd (HQ)  
 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit  
 Singapore 415875  
 Estimated Period of Repair: 7.0 days

---

**Adjuster:** CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                            | Condition           | Repairer's  | Amount       |
|-----|-----|----------|----------------------------------------|---------------------|-------------|--------------|
| 1   | 1   |          | *REAR DOOR LH                          | Dented              | 2,147.90 FL | *1,993.00 FL |
| 2   | 1   |          | *REAR DOOR LOCK CATCHER LH             | Not Necessary       | 19.30 FL    | *- FL        |
| 3   | 1   |          | *REAR DOOR INNER LOCK LH               | Not Necessary       | 386.40 FL   | *- FL        |
| 4   | 1   |          | *REAR DOOR INNER TRIM LH               | Not Necessary       | 489.00 FL   | *- FL        |
| 5   | 1   |          | *REAR DOOR FRAME WEATHERSTRIP LH       | Not Necessary       | 124.80 FL   | *- FL        |
| 6   | 1   |          | *REAR DOOR WEATHERSTRIP LH             | Not Necessary       | 106.00 FL   | *- FL        |
| 7   | 1   |          | *REAR DOOR POWER WINDOW MOTOR LH       | Not Necessary       | 160.50 FL   | *- FL        |
| 8   | 1   |          | *REAR DOOR INNER WATER SHIELD LH       | Not Necessary       | 78.50 FL    | *- FL        |
| 9   | 1   |          | *REAR DOOR OUTER STRIP LH              | Not Necessary       | 85.10 FL    | *- FL        |
| 10  | 1   |          | *REAR FENDER LH                        | Dented              | 1,892.00 FL | *1,892.00 FL |
| 11  | 1   |          | *REAR FENDER UPPER GARNISH LH          | Not Necessary       | 198.20 FL   | *- FL        |
| 12  | 1   |          | *REAR FENDER INNER PANEL LH            | Not Necessary       | 863.00 FL   | *- FL        |
| 13  | 1   |          | *REAR FENDER INNER COWLING LH          | Torn                | 189.20 FL   | *189.20 FL   |
| 14  | 1   |          | *REAR MUD FLAP LH                      | Not Necessary       | 154.20 FL   | *- FL        |
| 15  | 1   |          | *REAR ABS SENSOR LH                    | Not Necessary       | 394.50 FL   | *- FL        |
| 16  | 1   |          | *REAR WHEEL HUP C/W BEARING LH         | Jammed              | 452.30 FL   | *452.30 FL   |
| 17  | 1   |          | *REAR SHOCK ABSORBER LH                | Not Necessary       | 230.50 FL   | *- FL        |
| 18  | 1   |          | *REAR AXLE                             | Not Necessary       | 1,248.10 FL | *- FL        |
| 19  | 1   |          | *REAR BUMPER                           | Broken              | 520.80 FL   | *520.80 FL   |
| 20  | 1   |          | *REAR BUMPER LOWER (BLACK)             | Cut                 | 380.60 FL   | *380.60 FL   |
| 21  | 2   |          | *REAR BUMPER SIDE RETAINER             | Broken (1 PCS ONLY) | 97.80 FL    | *48.90 FL    |
| 22  | 4   |          | *REAR BUMPER BRACKET                   | Not Necessary       | 192.00 FL   | *- FL        |
| 23  | 2   |          | *REAR BUMPER REFLECTOR                 | Not Necessary       | 96.00 FL    | *- FL        |
| 24  | 1   |          | *REAR BUMPER REVERSE SENSOR LH         | Not Necessary       | 249.20 FL   | *- FL        |
| 25  | 4   |          | *REAR BUMPER REVERSE SENSOR HOLDER     | Necessary           | 192.00 FL   | *80.00 FL    |
| 26  | 2   |          | *REAR BLIND SPOT                       | Not Necessary       | 2,592.80 FL | *- FL        |
| 27  | 2   |          | *REAR BLIND SPOT BRACKET               | Not Necessary       | 338.60 FL   | *- FL        |
| 28  | 1   |          | *REAR BLIND SPOT WIRE HARNESS          | Not Necessary       | 658.00 FL   | *- FL        |
| 29  | 1   |          | *TAILLAMP (LH)                         | Cut                 | 956.00 FL   | *956.00 FL   |
| 30  | 1   |          | *SET REAR BUMPER CLIPS                 | Necessary           | 50.00 FS    | *30.00 FS    |
| 31  | 1   |          | *SET TAILLAMP CLIPS                    | Not Necessary       | 30.00 FS    | *- FS        |
| 32  | 1   |          | *SET REAR DOOR INNER TRIM BOARD CLIP   | Not Necessary       | 60.00 FS    | *- FS        |
| 33  | 1   |          | *REAR FENDER SEALANT LH                | Necessary           | 80.00 FS    | *30.00 FS    |
| 34  | 1   |          | *SET REAR FENDER COWLING CLIP          | Necessary           | 60.00 FS    | *20.00 FS    |
| 35  | 1   |          | *SET REAR FENDER INNER TRIM CLIP       | Not Necessary       | 60.00 FS    | *- FS        |
| 36  | 1   |          | *REAR WINDSCREEN SEALANT               | Necessary           | 80.00 FS    | *40.00 FS    |
| 37  | 1   |          | *REAR WINDSCREEN INNER SEAL            | Necessary           | 60.00 FS    | *30.00 FS    |
| 38  | 1   |          | *REAR WHEEL TYRE LH                    | Not Necessary       | 400.00 FS   | *- FS        |
| 39  | 1   |          | *REAR WHEEL RIM LH                     | Repair              | 850.00 FS   | *- FS        |
| 40  | 1   |          | *RR DOOR SEALANT LH                    | Necessary           | 120.00 FS   | *30.00 FS    |
| 41  | 1   |          | *RR FENDER UPPER GARNISH SEALANT LH    | Not Necessary       | 60.00 FS    | *- FS        |
| 42  | 1   |          | *LHR FENDER UPPER GARNISH INNER SHIELD | Not Necessary       | 60.00 FS    | *- FS        |
| 43  | 1   |          | *BRAKE OIL                             | Not Necessary       | 30.00 FS    | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                 |
|------------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>17,493.30</b> | <b>6,692.80</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b> | 3,098.66         | 1,302.56        |
| <b>Total Parts (\$\$)</b>                                  | <b>14,394.64</b> | <b>5,390.24</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                    | Lab.Type | Repairer's      | Amount          |
|---------------------------------|------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                                                |          |                 |                 |
| 1                               | PANEL BEATING ,REMOVING AND REPLACING PARTS                                                    | New      | 1,800.00        | 900.00          |
| 2                               | SPRAY PAINTING TO AFFECTED AREA                                                                | New      | 1,600.00        | 600.00          |
| 3                               | TUFF COAT                                                                                      | New      | 250.00          | 30.00           |
| 4                               | WIRING CHECK                                                                                   | New      | 80.00           | 30.00           |
| 5                               | TRANSFER REAR DOOR MECHANISM                                                                   | New      | 80.00           | 50.00           |
| 6                               | REMOVE AND REFIT FUEL TANK TO ASSIST REPAIR                                                    | New      | 120.00          | 0.00            |
| 7                               | REMOVE & REINSTALL REAR WINDOW GLASS                                                           | New      | 120.00          | 0.00            |
| 8                               | REMOVE AND REFIX REAR UNDER CARRIAGE                                                           | New      | 650.00          | 80.00           |
| 9                               | REMOVE AND REFIX REAR BLIND SPOT SENSOR AND SETTING                                            | New      | 800.00          | 0.00            |
| 10                              | RESET ABS LIGHT                                                                                | New      | 350.00          | 0.00            |
| 11                              | FOUR WHEEL ALIGNMENT                                                                           | New      | 120.00          | 80.00           |
| 12                              | REMOVE & REFIX REAR FENDER UPPER GARNISH                                                       | New      | 60.00           | 20.00           |
| 13                              | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC | New      | 180.00          | 0.00            |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                |          | <b>6,210.00</b> | <b>1,790.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >