

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PD 1240G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT PANEL	BADLY DENTED	8,500.00	3,619.80
1	FRONT WIPER ARM	NOT NECESSARY	450.00	-
1	FRONT GRILLE OUTER	CRACKED	2,110.00	1,866.10
1	FRONT GRILLE INNER	CRACKED	1,850.00	1,450.20
1	FRONT GRILLE LOGO	CRACKED	150.00	150.00
1	FRONT RADAR SENSOR COVER	CRACKED	450.00	280.00
1	FRONT RADAR SENSOR UNIT	SERVICEABLE	4,500.00	-
1	HEADLAMP N/S	CRACKED	2,680.00	2,495.90
1	HEADLAMP O/S	NOT NECESSARY	2,680.00	-
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,815.00	-
1	AIR CON BLOWER UNIT	CRACKED	4,855.00	1,850.00
1	AIR CON HEATER UNIT	CRACKED	5,209.00	3,599.20
1	FRONT CROSS MEMBER CENTRE	NOT NECESSARY	2,800.00	-
	LESS 25% DISCOUNT		-9,512.25	-3,827.80
			28,536.75	11,483.40
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REFIX FRONT WINDSCREEN.		200.00	150.00
	TO DISMANTLE & REFIX FRONT DASHBOARD.		480.00	300.00
	TO REFILL AIR CON GAS.		100.00	100.00
	TO SPRAY RUST PROOFING.		100.00	30.00
	TO DIAGNOSTIC & REPROGRAMME SYSTEM.		500.00	200.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		1,200.00	800.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	680.00
			4,130.00	2,280.00
	GRAND TOTAL		32,666.75	13,763.40

Report Ref No. CS/LPC24120102/Uvh3m4(N)



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	11,000.00
(TO ITS PRE-ACCIDENT CONDITION)	·

Report Ref No. CS/LPC24120102/Uvh3m4(N)

MARKET VALUE: \$150,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$44,239.00=NETT VALUE: \$105,761.00

CHUA KANG SENG

Licensed Appraiser