

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24120105/UPA3Q2
Date: 12/03/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002582_01
Claimant Vehicle No : SJR4382H Insured Vehicle No : SLF7719R
Date of Loss: 05/12/2024 Nature of Claim: TP Claim No: MFL2024D0014524

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJR4382H
Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4901465
Reg. Date: 24/06/2009 (Man. Year: 2009) Chassis No: MR053ZEE106147511
Colour: Beige Odometer: 489588 km
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Matrax 6 mm Rear Left Side: Matrax 6 mm
Front Right Side: Matrax 6 mm Rear Right Side: Matrax 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,292.52	10,736.20	13,556.32	55.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,250.00	2,800.00	3,450.00	55.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,542.52	13,536.20	17,006.32	55.68
Approved Total (Overridden) (S\$)		10,800.00		
Nett Amount (S\$)	30,542.52	10,800.00	19,742.52	64.64
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		11,247.25		
Global Sum Settlement (S\$)		11,200.00		

INSPECTION

Date of Assignment: 09/12/2024
Date Inspected: 09/12/2024 Inspected At: Choo Motor Spray Painter (HQ)
1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit
Singapore 417883
Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Feb 2025)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR4382H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	1,466.10 FL	*- FL
2	1		*BOOTLID REAR LOGO	Not Necessary	68.50 FL	*- FL
3	1		*BOOTLID COROLLA EMBLEM	Not Necessary	62.80 FL	*- FL
4	1		*BOOTLID ALTIS EMBLEM	Not Necessary	58.00 FL	*- FL
5	1		*BOOTLID INNER LOCK	Not Necessary	409.10 FL	*- FL
6	1		*BOOTLID 1.6 EMBLEM	Not Necessary	66.80 FL	*- FL
7	1		*BOOTLID WEATHERSTRIP	Not Necessary	282.30 FL	*- FL
8	1		*REAR BUMPER	Deformed / Torn	755.10 FL	*725.10 FL
9	1		*REAR BUMPER SPONGE	Serviceable	395.40 FL	*- FL
10	2		*REAR BUMPER REFLECTORS	Not Necessary	120.00 FL	*- FL
11	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	130.00 FL	*- FL
12	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
13	1		*REAR END PANEL	Repair	788.20 FL	*- FL
14	1		*REAR END PANEL TOP GARNISH	Not Necessary	362.30 FL	*- FL
15	2		*TAILLAMPS	Not Necessary	1,360.00 FL	*- FL
16	1		*REAR EXHAUST	Not Necessary	899.10 FL	*- FL
17	1		*BONNET	Dented / Bent	1,926.10 FL	*1,455.10 FL
18	1		*BONNET INNER RUBBER	Necessary	45.00 FL	*45.00 FL
19	2		*BONNET HINGES	Not Necessary	230.00 FL	*- FL
20	1		*BONNET INSULATOR	Not Necessary	281.00 FL	*- FL
21	1		*BONNET LOCK	Twisted	105.00 FL	*105.00 FL
22	1		*FRONT BUMPER	Torn	781.10 FL	*722.10 FL
23	2		*FRONT BUMPER SIDE RETAINERS	Bent	90.00 FL	*90.00 FL
24	1		*FRONT BUMPER CENTRE GRILLE	Torn	108.00 FL	*108.00 FL
25	1		*FRONT BUMPER BEAM	Bent	561.10 FL	*422.50 FL
26	1		*FRONT BUMPER SPONGE	Not fitted	140.10 FL	*- FL
27	2		*FRONT BUMPER FOG LAMPS	Cracked	722.00 FL	*722.00 FL
28	2		*FRONT BUMPER FOG LAMP COVERS	Serviceable	210.00 FL	*- FL
29	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
30	1		*FRONT GRILLE	Twisted	381.90 FL	*381.90 FL
31	1		*FRONT GRILLE LOGO	Necessary	68.50 FL	*68.50 FL
32	2		*HEADLAMP	Cracked	5,980.00 FL	*2,976.60 FL
33	1		*FRONT BRACE PANEL	Twisted	121.00 FL	*121.00 FL
34	2		*FRONT FENDERS	Repair	1,522.00 FL	*- FL
35	2		*FRONT FENDER INNER SHIELDS	Not Necessary	322.00 FL	*- FL
36	2		*FRONT FENDER VVTI EMBLEMS	Necessary	116.00 FL	*116.00 FL
37	1		*FRONT SUPPORT PANEL	Bent	2,160.00 FL	*1,660.10 FL
38	1		*FRONT SUPPORT PANEL TOP GARNISH	Twisted	210.00 FL	*210.00 FL
39	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FL	*- FL
40	1		*AIR CON CONDENSER	Bent / Punctured	2,413.10 FL	*1,810.10 FL
41	1		*AIR CON DISCHARGE HOSE	Serviceable	481.90 FL	*- FL
42	1		*AIR CON SUCTION HOSE	Serviceable	455.10 FL	*- FL
43	1		*AIR CON PIPE	Not Necessary	211.00 FL	*- FL
44	1		*AIR CLEANER BOX ASSY	Not Necessary	650.00 FL	*- FL
45	1		*RADIATOR	Bent / Twisted	2,901.10 FL	*2,422.60 FL
46	1		*RADIATOR FAN ASSY	Not Necessary	850.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
48	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	50.00 FS	*- FS
49	1		*SET REAR BUMPER REVERSE SENSOR	Serviceable	280.00 FS	*- FS
50	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS
51	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	250.00 FS	*- FS
52	1		*FRONT LICENCE PLATE	Bent / Cracked	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	32,146.70	14,301.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	7,854.18	3,565.40
Total Parts (\$\$)	24,292.52	10,736.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	30.00
3	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
4	TO DISMANTLE & REFIX BOOTLID MECHANISM	New	100.00	0.00
5	TO RESET & REPROGRAMME SYSTEM	New	100.00	0.00
6	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	0.00
7	TO CONDUCT WHEEL ALIGNMENT	New	100.00	0.00
8	TO REFILL AIR CON GAS	New	100.00	100.00
9	TO SPRAY RUST PROOFING	New	200.00	60.00
10	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	2,500.00	1,000.00
11	TO PUTTY & SPRAY PAINTING	New	2,800.00	1,580.00
Gross Labour Cost (\$\$)			6,250.00	2,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >