

ASS. REC. BY: Tawfik

REF: CD/LPC 24120108/Tma3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/ ☒ WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: **\$17K**

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seer: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum. Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBW 6035R Yr Regn: 2024, 07

Type: M. Car / M. C. ☒ / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai GT 125 c.c. 124

Colour: Red A/C: Insured / Std / NI / NA

Sb. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MLHSA 6578 P500 1157

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: PS / S/Rim / STD A/Rim or

Tyre Size: F: 80/90 R17

R: 100/80 R17

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or IRC

Front: _____ Rear: _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. _____ D.O.I. 10/12/24

Survey held at Evzat Lee WL

Des. of Damages ☒ / Rear / ☒ / ☒ / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1) _____
Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS. \$1 _____

Photos _____

Others _____

Report Format: _____

Lump Sum / L.B. / L.F. _____)

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-36/37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

ESTIMATE COST OF REPAIR

Date: 11-Dec-24

Estimate no. 1562

Plate No. FBW6035R

Model.

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	HANDLER BAR	\$ 225.00	?	
2	MIRRORS	\$ 38.00	cut ✓	
3	BRAKE LEVER RIGHT	\$ 30.00	cut ✓	
4	BALANCER RIGHT	\$ 40.00	cut ✓	
5	THROTTLE CABLE	\$ 110.00	dis ✓	
6	T-FORK	\$ 180.00	?	
7	FORK SET	\$ 225.00	?	
8	STEERING CONE	\$ 115.00	?	
9	GEAR PEDAL	\$ 40.00	bt ✓	
10	FOOTREST RIGHT	\$ 40.00	bt ✓	
11	COVER FOOTREST RIGHT	\$ 60.00	cut ✓	
12	PIPE PROTECTOR MUFFLER	\$ 60.00	dd ✓	
13	BODY ALIGNMENT	\$ 600.00	x	
14	FRONT FENDER FENDER Fender	\$ 80.00	bt ✓	
15	REFLECTOR	\$ 20.00	cut ✓	
16	RIM HEAD LAMP	\$ 110.00	cut ✓	
17	HEAD LIGHT UNIT	\$ 305.00	cut ✓	
18	CASE HEAD LIGHTS	\$ 80.00	x	
19	NUMBER PLATE	\$ 10.00	bt ✓	
20	BRAKE PEDAL	\$ 60.00	bt ✓	
21	LABOUR	\$ 600.00	350	

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495749/62563561

wp 10/12/24 @ 430pm 3 days

taufik@lkhands.com

Less 10% \$ 302.80

\$ 3,028.00

Sub Total : \$ 2,725.20

GST 9% \$ 245.27

Total: \$ 2,970.47

Estimate given are base on visible damages ONLY before dismantling of the vehicle

This is computer generated no signature is required.