

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG24120110/EANH3E2
Date: 29/08/2025

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30003855914		
Claimant Vehicle No :	SLQ5383E	Insured Vehicle No :	GBJ7831X		
Date of Loss:	09/12/2024	Nature of Claim:	TP	Claim No:	384221

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ5383E	Engine No:	G4FJHU532317
Make & Model:	HYUNDAI TL TUCSON, 1.6 GLS T-GDI DCT 2WD (A)	Chassis No:	KMHJ3812VJU529755
Reg. Date:	14/07/2017 (Man. Year: 2017)	Odometer:	110528 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,086.96	8,673.92	7,413.04	46.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,710.00	2,680.00	3,030.00	53.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,796.96	11,353.92	10,443.04	47.91
Approved Total (Overridden) (S\$)		9,000.00		
Nett Amount (S\$)	21,796.96	9,000.00	12,796.96	58.71

INSPECTION

Date of Assignment:	11/12/2024	Ms Car Auto Pte Ltd (HQ)
Date Inspected:	09/12/2024 Inspected At:	8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT
Estimated Period of Repair:	9.0 days	Singapore 415875

Adjuster: ADRIAN LING Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Aug 2025)
Parts:	143	HYUNDAI TL TUCSON 1.6 GLS T-GDI DCT 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ5383E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	496.50 FL	*496.50 FL
2	1		*REAR BUMPER SIDE HOLDER	Cracked	39.40 FL	*39.40 FL
3	1		*REAR BUMPER REFLECTOR	Cracked	198.30 FL	*198.30 FL
4	1		*REAR BUMPER LOWER GARNISH	Deformed	351.40 FL	*351.40 FL
5	1		*REAR BUMPER REINFORCEMENT	Cracked	352.90 FL	*352.90 FL
6	5		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	92.00 FL	*- FL
7	1		*REAR BUMPER SENSOR	Damaged	210.40 FL	*210.40 FL
8	4		*REAR BUMPER SENSOR HOLDER	Necessary	100.00 FL	*100.00 FL
9	1		*REAR BUMPER SENSOR WIRE HARNESS	Not Necessary	367.30 FL	*- FL
10	1		*REAR BUMPER MUDFLAP	Not Necessary	39.40 FL	*- FL
11	1		*TAILLAMP	Cracked	893.30 FL	*893.30 FL
12	1		*TAILLAMP PANEL	Dented	393.80 FL	*393.80 FL
13	1		*REAR END PANEL	Repair	739.10 FL	*- FL
14	1		*REAR END PANEL TOP GARNISH	Not Necessary	185.40 FL	*- FL
15	1		*TAILGATE	Repair	1,758.90 FL	*- FL
16	1		*TAILGATE LOCK C/W MOTOR	Not Necessary	677.60 FL	*- FL
17	1		*TAILGATE WEATHERSTRIPE	Not Necessary	175.90 FL	*- FL
18	1		*TAILGATE REFLECTOR	Not Necessary	650.90 FL	*- FL
19	1		*TAILGATE OUTER GARNISH	Repair	310.40 FL	*- FL
20	1		*TAILGATE OUTER GARNISH TOP BRACKET	Not Necessary	96.20 FL	*- FL
21	1		*TAILGATE OUTER GARNISH LOWER BRACKET	Not Necessary	89.60 FL	*- FL
22	1		*TAILGATE INNER TRIM BOARD	Not Necessary	352.60 FL	*- FL
23	1		*TAILGATE GLASS MOULDING	Not Necessary	210.30 FL	*- FL
24	1		*HYUNDAI LOGO	Necessary	45.90 FL	*45.90 FL
25	1		*TUCSON WORDING	Necessary	60.50 FL	*60.50 FL
26	1		*TURBO WORDING	Necessary	61.40 FL	*61.40 FL
27	1		*S EMBLEM	Necessary	45.80 FL	*45.80 FL
28	1		*REAR FENDER	Distorted	2,241.90 FL	*2,241.90 FL
29	1		*REAR FENDER BLIND SPOT MODULE	Not Necessary	1,678.10 FL	*- FL
30	1		*REAR FENDER BLIND SPOT MODULE BRACKET	Bent	72.40 FL	*72.40 FL
31	1		*REAR FENDER AIR VENT	Deformed	60.90 FL	*60.90 FL
32	1		*REAR FENDER ARC GARNISH	Missing	67.70 FL	*67.70 FL
33	1		*REAR FENDER INNER TRIM BOARD	Not Necessary	342.60 FL	*- FL
34	1		*REAR FENDER INNER SHIELD	Deformed	264.20 FL	*264.20 FL
35	1		*FUEL LID COVER	Damaged	198.40 FL	*198.40 FL
36	1		*REAR SHOCK ABSORBER	Bent	585.60 FL	*585.60 FL
37	1		*REAR KNUCKLE ARM	Damaged	485.70 FL	*485.70 FL
38	1		*REAR WHEEL HUB C/W BEARING	Damaged	401.10 FL	*401.10 FL
39	1		*REAR LOWER ARM	Bent	510.70 FL	*510.70 FL
40	1		*REAR CONTROL ARM	Bent	204.60 FL	*204.60 FL
41	1		*REAR TRAILING ARM	Bent	574.60 FL	*574.60 FL
42	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR BUMPER LOWER SPOILER	Smashed	1,200.00 FS	*800.00 FS
44	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
45	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
46	1		*SET TAILGATE OUTER GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
47	1		*SET TAILGATE INNER TRIM CLIPS	Not Necessary	30.00 FS	*- FS
48	1		*TAILGATE GLASS SEALANT	Not Necessary	60.00 FS	*- FS
49	1		*SET REAR FENDER ARC GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
50	1		*SET REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	30.00 FS	*- FS
51	1		*SET REAR FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
52	1		*REAR FENDER SEALANT	Necessary	60.00 FS	*60.00 FS
53	1		*REAR WHEEL RIM	Cut	880.00 FS	*400.00 FS
54	1		*REAR TYRE	Punctured	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	19,423.70	10,457.40
- List Item Discount on L Items 20.00/20.00% (S\$)	3,336.74	1,783.48
Total Parts (S\$)	16,086.96	8,673.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVE AND REFIT PARTS	New	2,000.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,600.00	800.00
3	WIRING CHECK	New	100.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE UPHOLSTERY	New	150.00	60.00
6	TO SPRAY TUFF COAT	New	150.00	100.00
7	TO REMOVE TAILGATE FITTINGS	New	150.00	0.00
8	TO REMOVE TAILGATE GLASS	New	180.00	0.00
9	TO REMOVE REAR UNDERCARRIAGE	New	350.00	200.00
10	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
11	TO REPROGRAMME BLIND SPOT MODULE	New	480.00	350.00
12	TO REMOVE FUEL TANK	New	150.00	60.00
13	TOWING (KING ROLLER)	New	150.00	150.00
Gross Labour Cost (S\$)			5,710.00	2,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >