

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/III24120112/UNH3E2(N)  
**Date:** 25/03/2025REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MFL0003414_05
<b>Claimant Vehicle No :</b>	GBL5873C	<b>Insured Vehicle No :</b>	SMR3621P
Date of Loss:	06/12/2024	Nature of Claim:	TP
		Claim No:	MFL2024D0014638

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBL5873C</b>		
Make & Model:	TOYOTA DYNA, 3.0 D (A)	Engine No:	1KDB079068
Reg. Date:	12/11/2021 (Man. Year: 2021)	Chassis No:	KDY2318047707
Colour:	White	Odometer:	123137 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	235/50 R14 (D)
Front Left Side:	Michelin 6 mm	Rear Left Side:	Delium 6/6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Delium 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,553.80	835.62	1,718.18	67.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,870.00	540.00	1,330.00	71.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,423.80</b>	<b>1,375.62</b>	<b>3,048.18</b>	<b>68.90</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,100.00</b>		
<b>Nett Amount (S\$)</b>	<b>4,423.80</b>	<b>1,100.00</b>	<b>3,323.80</b>	<b>75.13</b>

INSPECTION

Date of Assignment:	09/12/2024	
Date Inspected:	20/03/2025 Inspected At:	HH MOTOR TRADING (HQ) BLK 3012 BEDOK NORTH AVE 4 #01-2054 BEDOK INDUSTRIAL PARK E Singapore 489978
Estimated Period of Repair:	3.0 days	

**Adjuster:** MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 25 Mar 2025)	
Parts:	N/A	TOYOTA DYNA 3.0 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL5873C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL LAMP LH	Cracked	465.30 F	*322.30 FL
2	1		*REAR TAIL LAMP PANEL LH	Bent	125.20 F	*125.20 FL
3	1		*REAR TAIL LAMP REFLECTOR LH	Not Necessary	79.20 F	*- FL
4	1		*REAR END PANEL	Repair	606.10 F	*- FL
5	1		*SET REAR REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
6	1		*REAR BOX DOOR PILLAR LH	Dented / Bent	980.00 FS	*500.00 FS
7	1		*SPEED STICKER 70KM/HR	Not Necessary	18.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	2,553.80 947.50
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00 111.88
					Total Parts (\$\$)	2,553.80 835.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CARRY OUT ANTI-RUST TREATMENT	New	120.00	0.00
2	REWIRING TO FACILITATE REPAIRS	New	150.00	20.00
3	LABOUR TO REMOVE AND REPLACE STAINLESS STEEL FLOOR PANEL. SIDE PANEL, DOOR PILLARS, DOORS AND ALL NECESSARY AND AFFECTED AREAS CAUSED BY ACCIDENT	New	800.00	320.00
4	SPRAY PAINTING MATERIALS AND RESPRAY OF ALL AFFECTED AND REPLACED PARTS NECESSARY FOR PAINTWORK	New	800.00	200.00
<b>Gross Labour Cost (S\$)</b>			<b>1,870.00</b>	<b>540.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >