

ASS. REC. BY:

REF:

F021

CS/FCI 24120116/Knh3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 883k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMH 8724X Yr Regn: 02, 19Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Camry C.G. 1998Colour: M. Grey A/C: Insured / Std / NI / NASp. Reading: 45268 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NR 2BN314K 704 001813Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rlm / STD / A/Rlm orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 5/12/24

Rear

R/Bal. 9 mmL/Bal. 9 mmD.O.I. 10/12/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop orN/S body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

31/12 21:00 @ 5450d Coln (Red, \$ 28962.59, 8470)

LTA: \$ 38701

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: _____

Survey Fee:

Transportation

) S + RS. \$

) Frt

) Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

1st Capital

Pr 6/12 @ 24



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Repair Estimates

SMH 8724 X

Parts	(a) Cost / List Price Items	\$	23,658.07
	Plus/Less 25%	\$	5,914.52
	Total of Cost / List	\$	29,572.59
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	700.00
Total Parts Cost		\$	30,272.59
Labour		\$	4,140.00
Total		\$	34,412.59

Not Authorized
11 Pm @ 5450h
Morning After Rain

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 9% G.S.T.

Name of Surveyor : Kennerh
Company : LKK
Survey conducted on : 10/12/24 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 06 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor :  Date: 10/12/24

**ESTEEM**

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Spare Parts

Vehicle No. : **SMH8724X**
Make & Model : TOYOTA CAMRY 4-DOOR SEDAN (AUTO) 2.0
Chassis No : MR2BN3HK704001813

Submit By : _____
Year Manufacture : 13-Feb-19
Engine No. : _____
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH front fender <i>Bt</i>	1	\$1,318.90		✓
2	LH front fender undershield <i>Sh</i>	1	\$392.00		X
3	LH front fender undershield clip <i>na</i>	10	\$50.00		X
4	LH front door <i>Bt/warp</i>	1	\$2,573.90		✓
5	LH front door hinge top <i>R</i>	1	\$135.40		X
6	LH front door hinge bottom <i>R</i>	1	\$135.40		X
7	LH front door lock <i>R</i>	1	\$840.30		X
8	LH front door checker <i>Sh</i>	1	\$305.00		X
9	LH front door weatherstrip <i>Sh</i>	1	\$335.00		X
10	LH front door trim <i>Sh</i>	1	\$1,581.30		X
11	LHF door glass outer moulding <i>Sh</i>	1	\$227.70		X
12	LHF power window motor <i>Sh</i>	1	\$1,273.00		X
13	LHF power window regulator <i>Sh</i>	1	\$354.50		X
14	LH rear door <i>Bt/warp</i>	1	\$2,236.20		✓
15	LH rear door hinge top <i>R</i>	1	\$135.40		X
16	LH rear door hinge bottom <i>R</i>	1	\$135.40		X
17	LH rear door lock <i>R</i>	1	\$779.30		X
18	LH rear door weatherstrip <i>Sh</i>	1	\$311.67		X
19	LH rear door trim <i>Sh</i>	1	\$1,331.90		X
20	LHR door glass outer moulding <i>Sh</i>	1	\$157.50		X
21	LHR power window motor <i>Sh</i>	1	\$1,273.00		X
22	LHR power window regulator <i>Sh</i>	1	\$341.70		X
23	LH rear fender <i>R</i>	1	\$1,559.40		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SMH8724X** Submit By : **0**
Make & Model : **TOYOTA CAMRY 4-DOOR SEDAN (AUTO) 2.0** Year Manufacture : **43509**
Chassis No : **MR2BN3HK704001813** Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	LH rear fender undershield <i>sch</i>	1	\$272.80		X
25	LH rear fender undershield clip <i>sch</i>	10	\$50.00		X
26	LH front rim <i>sch</i>	1	\$2,775.70		X
27	LH front tyre <i>sch</i>	1	\$350.00	SN	X
28	LH rear rim <i>sch</i>	1	\$2,775.70		X
29	LH rear tyre <i>sch</i>	1	\$350.00	SN	X
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP

385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP

176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Labour

Vehicle No. : **SMH8724X** Submit By : **0**
Make & Model : **CAMRY 4-DOOR SEDAN (AUTO)** Year of Manufacture : **13-Feb-19**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(FRONT BUMPER,LHF FENDER,LHF DOOR,LHR DOOR,LHR FENDER,REAR BUMPER,LHF RIM,LHR RIM)	\$1,600.00	<i>Food</i>
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(FRONT BUMPER,LHF FENDER,LHF DOOR,LHR DOOR,LHR FENDER,REAR BUMPER,LHF RIM,LHR RIM)	\$1,600.00	<i>1200</i>
3	To check wiring	\$50.00	<i>20</i>
4	To do wheel alignment.	\$120.00	<i>60</i>
5	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$150.00	<i>120</i>
6	To tuff coat.	\$200.00	<i>90</i>
7	To remove & refit inner seat & upholstery to assist work load. <i>nn</i>	\$150.00	<i>X</i>
8	To remove & refit roof lining, inner trim to assist work load. <i>nn</i>	\$150.00	<i>X</i>
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	<i>20</i>

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.