

SMH 8724 X

Repair Estimates 23,658.07 Parts (a) Cost / List Price Items \$ 5,914.52 Plus/Less ___25% 29,572.59 Total of Cost / List (b) Nett Price Items Less **Total of Nett Item** 700.00 (c) Special Nett Items 30,272.59 **Total Parts Cost** 4,140.00 Labour 34,412.59 \$ Total

ESTEEM PERFORMANCE PTE LTD UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP

385 Sin Ming Drive Singapore 575718 (T) 6753 2112 ((F) 6451 0394

WORKSHOP

176 Sin Ming Drive Sin Ming Auto Care #01-14 , #01-15 , #01-16 Singapore 575721 (T) 6484 1221 (F) 6484 7829

Not Authorite
11 Pap & 5450h
Ruhmy After Painy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
 To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 9% G.S.T.

			11
Nam	e of Surveyor	:	Rennerh
Com	pany	*	- L/C/C
Surv	ey conducted on	:	at
/	narks By Surveyor		
(a)	The repair of this vehicle is author	rized	/ is not authorized until further notice.
(b)	Recommended Days of Repair		day(s)
(c)	Resurvey	ŧ	Required / Not Required
(d)	Excess	:\$_	10/12/26
(e)	Signature of surveyor	:	



ESTEEM PERFORMANCE PTE LTD UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP

385 Sin Ming Drive Singapore 575718 (T) 6753 2112 (F) 6451 0394

WORKSHOP

176 Sin Ming Drive Sin Ming Auto Care #01-14 , #01-15 , #01-16

Singapore 575721 (T) 6484 1221 (F) 6484 7829

Spare Parts

Vehicle No. : Make & Model:

Chassis No :

SMH8724X

TOYOTA CAMRY 4-DOOR SEDAN (AUTO) 2.0

MR2BN3HK704001813

Submit By

Year Manufacture:

13-Feb-19

Engine No. :

Cost / List

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
1	LH front fender	B	1	\$1,318.90		
2	LH front fender undershield	Sn	1	\$392.00		
3	LH front fender undershield clip	Na	10	\$50.00		X
4	LH front door	31/way	1	\$2,573.90		
5	LH front door hinge top	n	1	\$135.40		<u> </u>
6	LH front door hinge bottom	1	1	\$135.40		X
7	LH front door lock	N	1	\$840.30		X
8	LH front door checker	Su	1	\$305.00		X
9	LH front door weatherstip	Se	1	\$335.00		
10	LH front door trim	34	. 1	\$1,581.30		X
11	LHF door glass outer moulding	Sz	. 1	\$227.70		X
12	LHF power window motor	Sz	- 1	\$1,273.00		X
13	I HF power window regulator	ſ.	_ 1	\$354.50		X
14	LH rear door	Bylvon	1	\$2,236.20		
15	LH rear door hinge top	n	1	\$135.40		X
16	LH rear door hinge bottom	1	7 1	\$135.40		
17	LH rear door lock	1	1	\$779.30		×
18	LH rear door weatherstip	Sz	1	\$311.67		X
19	LH rear door trim	Se	1	\$1,331.90		×
20	LHR door glass outer moulding	S	1	\$157.50		
21	LHR power window motor	s	1	\$1,273.00		X
22	LHR power window regulator		n 1	\$341.70		X
23	LH rear fender		N 1	\$1,559.40		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No.

SMH8724X

Submit By

43509

Make & Model: Chassis No :

TOYOTA CAMRY 4-DOOR SEDAN (AUTO) 2.(Year Manufacture: MR2BN3HK704001813

Engine No.

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	LH rear fender undershield	Sin 1	\$272.80		X
25		en 10	\$50.00		X
26	LH front rim Sch	N 1	\$2,775.70		X
27	LH front tyre	In 1	\$350.00	SN	X
28	LH rear rim	·Sn1	\$2,775.70		X
29	LH rear tyre	P 1	\$350.00	SN	X
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP 385 Sin Ming Drive Singapore 575718

(T) 6753 2112 (F) 6451 0394

WORKSHOP

176 Sin Ming Drive Sin Ming Auto Care #01-14 , #01-15 , #01-16 Singapore 575721 (T) 6484 1221 (F) 6484 7829

Labour

Vehicle No.	:	SMH8724X	Submit By	:	0	
Make & Model	:	CAMRY 4-DOOR SEDAN (AL	JTO) Year of Manufac	ture:	13-Feb-19	

Labour Description	Esimated Price	Adjusted Price
TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
REPAIR AREA.(FRONT BUMPER, LHF FENDER, LHF DOOR, LHR		
DOOR,LHR FENDER,REAR BUMPER,LHF RIM,LHR RIM)	\$1,600.00	Tod
		12001
DOOR,LHR FENDER,REAR BUMPER,LHF RIM,LHR RIM)	\$1,600.00	12001
To check wiring	\$50.00	201
To do wheel alignment.	\$120.00	601
To remove & refit Door trim, door glass, window regulator,		
door lock to assist work load.	\$150.00	120(
To tuff coat.	\$200.00	901
	nann comprimerter	
	\$150.00	×
load.		
To remove & refit roof lining, inner trim to assist work load.	\$150.00	Х
To conduct water leakage tests to ensure proper air and		
sealing	\$120.00	201
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER,LHF FENDER,LHF DOOR,LHR DOOR,LHR FENDER,REAR BUMPER,LHF RIM,LHR RIM) TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER,LHF FENDER,LHF DOOR,LHR DOOR,LHR FENDER,REAR BUMPER,LHF RIM,LHR RIM) To check wiring To do wheel alignment. To remove & refit Door trim, door glass, window regulator, door lock to assist work load. To tuff coat. To remove & refit inner seat & upholstery to assist work load. To remove & refit roof lining, inner trim to assist work load.	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(FRONT BUMPER,LHF FENDER,LHF DOOR,LHR DOOR,LHR FENDER,REAR BUMPER,LHF RIM,LHR RIM) \$1,600.00 TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(FRONT BUMPER,LHF FENDER,LHF DOOR,LHR DOOR,LHR FENDER,REAR BUMPER,LHF RIM,LHR RIM) \$1,600.00 To check wiring \$50.00 To do wheel alignment. \$120.00 To remove & refit Door trim, door glass, window regulator, door lock to assist work load. \$150.00 To tuff coat. \$200.00 To remove & refit inner seat & upholstery to assist work \$150.00 load. \$150.00 To remove & refit roof lining, inner trim to assist work load. \$150.00

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.