

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/III24070009/UPA3Q2**Date:** 15/11/2024**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549\_04  
**Claimant Vehicle No :** FBH3806G **Insured Vehicle No :** YR1029X  
Date of Loss: 25/06/2024 Nature of Claim: TP Claim No: MFL2024D0008169

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **FBH3806G**  
Make & Model: HONDA WW150, 153cc Engine No: HIDDEN  
Reg. Date: 05/06/2013 (Man. Year: 2013) Chassis No: MLHKF12A9C5002854  
Colour: Silver Odometer: 68465 km  
Engine Capacity: 153 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 90-90-14 Rear Tyre Size: 100-90-14  
Front Left Side: Michelin 0 mm Rear Left Side: Michelin 0 mm  
Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,876.00	1,577.00	299.00	15.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,577.00	780.00	797.00	50.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,453.00</b>	<b>2,357.00</b>	<b>1,096.00</b>	<b>31.74</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,850.00</b>		
<b>(S\$)</b>	3,453.00	1,850.00	1,603.00	46.42
<b>+ GST 9.00/9.00% (S\$)</b>	310.77	166.50	144.27	46.42
<b>Nett Amount (S\$)</b>	<b>3,763.77</b>	<b>2,016.50</b>	<b>1,747.27</b>	<b>46.42</b>
<b>+ Loss of Use (3.0 x S\$20.00/day) (S\$)</b>		60.00		
<b>+ Doc/Search Fee (S\$)</b>		27.25		
<b>Nett Liability (S\$)</b>		<b>2,103.75</b>		

**INSPECTION**

Date of Assignment: 02/07/2024  
Date Inspected: 02/07/2024 Inspected At: Ban Hock Hin Co. Pte Ltd (HQ)  
Industrial City  
Singapore 533758  
Estimated Period of Repair: 3.0 days

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 04 Nov 2024)	
Parts:	N/A	HONDA WW150 153cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBH3806G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOOTREST LH	Cut	85.00 F	*85.00 FL
2	1		*COVER FRONT UPPER	Cracked	85.00 F	*85.00 FL
3	1		*COVER SIDE LOWER LH	Cut	85.00 F	*85.00 FL
4	1		*COWLING FRONT LH	Cracked	162.00 F	*162.00 FL
5	1		*HEADLAMP ASSY	Cracked	778.00 F	*778.00 FL
6	1		*MIRROR LH	Damaged	40.00 F	*40.00 FL
7	1		*MUDGUARD FRONT (WHITE)	Crumpled	91.00 F	*91.00 FL
8	1		*STAND MAIN	Repair	78.00 F	*- FL
9	1		*STAND SIDE	Repair	38.00 F	*- FL
10	1		*STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT	Necessary	30.00 FS	*20.00 FS
11	1		*WINDSHIELD (GIVI)	Cracked	404.00 F	*404.00 FL
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	1,876.00 1,750.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 173.00
					Total Parts (\$\$)	1,876.00 1,577.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR DISMANTLING AND INSTALLATION OF PARTS.	New	510.00	300.00
2	SPRAY PAINT COVER SETS AND REAR BOX.	New	1,067.00	480.00
Gross Labour Cost (S\$)			1,577.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >