

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

**Our File No:** CS/AIG24120117/EVH3M4**Date:** 27/02/2025REFERENCE

Insured/Claimant:	LOW CHIN CHYE	Policy No:	2070148447	
Date of Loss:	08/12/2024	Nature of Claim:	OD	Claim No: 8998604702SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SDM8800P</b>		
Make & Model:	AUDI A3 SB, 1.4 TFSI COD S TRONIC (17") (A)	Engine No:	CZE866150
Reg. Date:	23/10/2020 (Man. Year: 2020)	Chassis No:	WAUZZZ8V4LA084000
Colour:	Blue	Odometer:	23338 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$108,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 ZR17	Rear Tyre Size:	225/45 ZR17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,642.00	9,056.64	4,585.36	33.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,172.00	9,747.00	4,425.00	31.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>27,814.00</b>	<b>18,803.64</b>	<b>9,010.36</b>	<b>32.40</b>
<b>- Excess (S\$)</b>	3,100.00	3,100.00	0.00	0.00
<b>(S\$)</b>	24,714.00	15,703.64	9,010.36	36.46
<b>+ GST 9.00/9.00% (S\$)</b>	2,224.26	1,413.33	810.93	36.46
<b>Nett Amount (S\$)</b>	<b>26,938.26</b>	<b>17,116.97</b>	<b>9,821.29</b>	<b>36.46</b>

INSPECTION

Date of Assignment: 09/12/2024

Date Inspected: 12/12/2024 Inspected At:

PREMIUM AUTOMOBILES PTE LTD (HQ)  
55 UBI ROAD 1  
SINGAPORE 408699

Estimated Period of Repair: 12.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	2,483.00 FS	*1,986.40 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	216.00 FS	*- FS
3	2		*REAR BUMPER LOCKING MECHANISM - LH /RH	Not Necessary	36.00 FS	*- FS
4	2		*REAR WHEEL HOUSING LINER ADAPTER - LH /RH	Not Necessary	96.00 FS	*- FS
5	1		*REAR BUMPER SPOILER	Not Necessary	297.00 FS	*- FS
6	1		*REAR BUMPER REFLECTOR - LH	Not Necessary	41.00 FS	*- FS
7	1		*REAR BUMPER GUIDE SECTION - LH	Broken	84.00 FS	*66.96 FS
8	1		*REAR SIDE PANEL - LH	Dented	5,131.00 FS	*4,104.80 FS
9	1		*REAR WHEEL HOUSING LINER - LH	Not Necessary	289.00 FS	*- FS
10	1		*REAR WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	67.00 FS	*- FS
11	1		*REAR OUTER TAIL LIGHT - LH	Broken	1,656.00 FS	*1,324.80 FS
12	1		*REAR QUARTER GLASS - LH	Necessary	365.00 FS	*291.60 FS
13	1		*REAR QUARTER GLASS CHROME TRIM STRIPS - LH	Necessary	326.00 FS	*260.40 FS
14	1		*REAR ROOF CHROME MOULDING - LH	Not Necessary	741.00 FS	*- FS
15	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
16	1		*METAL FILTER POWDER	Necessary	280.00 FS	*280.00 FS
17	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
18	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
19	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
20	1		*SUNDRIES	Necessary	800.00 FS	*34.88 FS
21	1		*SOUND ABSORBER (Supplementary)	Necessary	134.00 FS	*106.80 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$) 13,642.00 9,056.64**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID	New	280.00	280.00
2	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,600.00	1,600.00
3	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOFLINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,600.00	1,600.00
4	TO DISMANTLE AND RENEW REAR BUMPER. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,900.00	3,000.00
5	TO RESPRAY REAR BUMPER, LHS REAR FENDER, REAR END PANELLING, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL AND DOOR ENTRANCE	New	4,600.00	2,475.00
6	TO RENEW LHS 1/4 GLASS AND CARRY OUT WATER SEEPAGE TEST	New	500.00	500.00
7	TO INSTALL SOLAR FILM FOR LHS 1/4 GLASS	New	400.00	0.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
<b>Gross Labour Cost (\$\$)</b>			<b>14,172.00</b>	<b>9,747.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >