

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/AIG24120118/EMA3Q2
Date: 19/06/2025

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7240189921		
Claimant Vehicle No :	SFJ5511K	Insured Vehicle No :	GW5757M		
Date of Loss:	06/12/2024	Nature of Claim:	TP	Claim No:	5374147649SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFJ5511K	Engine No:	27492031015370
Make & Model:	MERCEDES-BENZ E300, 2.0 AMG (A)	Chassis No:	WDD2383482F004362
Reg. Date:	28/12/2017 (Man. Year: 2017)	Odometer:	76158 km
Colour:	White		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/35 R19	Rear Tyre Size:	275/35 R19
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,891.93	9,575.37	10,316.56	51.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,000.00	1,720.00	2,280.00	57.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,891.93	11,295.37	12,596.56	52.72
Approved Total (Overridden) (S\$)		9,000.00		
Nett Amount (S\$)	23,891.93	9,000.00	14,891.93	62.33
+ Loss of Use (7.0 x S\$120.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		9,867.25		
Global Sum Settlement (S\$)		9,860.00		

INSPECTION

Date of Assignment:	10/12/2024	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit Singapore 417883
Date Inspected:	10/12/2024 Inspected At:	
Estimated Period of Repair:	6.0 days	

Adjuster: CHEN TSUE YEE Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	3,257.95 FL	*2,750.00 FL
2	2		*REAR BUMPER SIDE HOLDER	Not Necessary	308.20 FL	*- FL
3	1		*REAR BUMPER REVERSE SENSOR (6 PCS)	Damaged (2 PCS ONLY)	1,469.70 FL	*489.90 FL
4	1		*REAR BUMPER REFLECTOR	N/S Cracked	110.40 FL	*55.20 FL
5	1		*REAR BUMPER LOWER LIP	Deformed	732.55 FL	*732.55 FL
6	1		*REAR BUMPER TOWING HOOK COVER	Not Necessary	132.25 FL	*- FL
7	1		*REAR BUMPER LOWER LIP MOULDING	Cut	404.80 FL	*404.80 FL
8	1		*REAR BUMPER REINFORCEMENT	Dented	1,443.25 FL	*1,260.00 FL
9	1		*REAR BUMPER CLIPS	Necessary	69.00 FL	*30.00 FL
10	1		*REAR NUMBER PLATE	Cracked	115.00 FL	*50.00 FL
11	1		*REAR NUMBER PLATE HOLDER	Not Necessary	34.50 FL	*- FL
12	2		*REAR NUMBER PLATE LAMP	Cracked	80.50 FL	*80.50 FL
13	1		*REAR END PANEL	Dented	2,219.50 FL	*1,650.00 FL
14	1		*REAR END PANEL TOP GARNISH	Deformed	241.50 FL	*241.50 FL
15	1		*REAR BOOTLID	Not Necessary	4,066.40 FL	*- FL
16	1		*REAR BOOTLID E300 EMBLEM	Not Necessary	170.20 FL	*- FL
17	1		*REAR BOOTLID SIDE LAMP	N/S Cut	2,116.00 FL	*1,058.00 FL
18	1		*REAR LAMP	N/S Cut	2,596.70 FL	*1,298.35 FL
19	2		*REAR EXHAUST PIPE CHROME	Not Necessary	1,147.70 FL	*- FL
20	2		*REAR BUMPER BRACKET	Not Necessary	703.80 FL	*- FL
21	1		*REAR NUMBER PLATE LAMP INNER GARNISH	Not Necessary	143.75 FL	*- FL
22	1		*REAR BUMPER LOWER LIP INNER GARNISH	Deformed	287.50 FL	*287.50 FL
23	1		*REAR BUMPER CENTRE GUIDE	Deformed	251.00 FL	*251.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	22,102.15	10,639.30
- List Item Discount on L Items 10.00/10.00% (\$)	2,210.22	1,063.93
Total Parts (\$)	19,891.93	9,575.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SUPPLY REAR END PANEL INNER SEALANT	New	200.00	60.00
2	REMOVE +REINSTALL REVERSE SENSOR	New	200.00	50.00
3	REMOVE+REINSTALL BOOTLID INNER GARNISH	New	200.00	0.00
4	REMOVE+REINSTAL EXHAUST PIPE	New	200.00	0.00
5	REMOVE+REPLACE REPAIR CONSISTENT TO THE ACCIDENT	New	1,800.00	800.00
6	RESPRAY PAINTING	New	1,300.00	750.00
7	TUFF KOTE	New	100.00	60.00
Gross Labour Cost (\$\$)			4,000.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >