12/16/24, 3:24 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS24120119/ENH3E2

16/12/2024 Date:

REFERENCE

Handling Insurer: **ECICS Limited** Policy No:

Claimant Vehicle

SH6681C Insured Vehicle No: SKT9025J No .

Date of Loss: 05/12/2024 Nature of Claim: TP Claim No: DMPU2400087H/02/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SH6681C

HYUNDAI SX2 KONA, 1.6 GDI HEV (A) G4LLRU424745 Make & Model: Engine No:

Reg. Date: 28/06/2024 (Man. Year: 2024) Chassis No: KMHHB811VRU067991

Colour: Blue Odometer: 55427 km

1580 cc **Engine Capacity:**

Market Value/New Car

N/A Price:

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Yes Footbrake (Serviceable):

Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R16 205/65 R16 Rear Tyre Size: Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,792.00	2,792.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	940.00	60.00	6.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,792.00	3,732.00	60.00	1.58
+ GST 9.00/9.00% (S\$)	341.28	335.88	5.40	1.58
Nett Amount (S\$)	4,133.28	4,067.88	65.40	1.58

INSPECTION

Date of Assignment: 10/12/2024

ComfortDelGro Engineering Pte Ltd (Loyang) Date Inspected: 10/12/2024 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: **CHEN TSUE YEE** Manager: **HUEY YON**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

12/16/24, 3:24 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Dec 2024)

Parts: 192 HYUNDAI SX2 KONA 1.6 GDI HEV (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SH6681C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER - FRT BUMPER LWR	Cut	1,100.00 FL	*1,100.00 FL
2	1		*LAMP ASSY - HEAD LH	Cut	2,216.00 FL	*2,216.00 FL
3	1		*GARNISH ASSY - FNDR SIDE LH	Cut	174.00 FL	*174.00 FL
F=Fra	nchise	part. L=ListItem	nDisc.			
				Sub Total (S\$)	3,490.00	3,490.00
			- List Item Discount on	L Items 20.00/20.00% (S\$)	698.00	698.00
				Total Parts (S\$)	2,792.00	2,792.00
			Report was unsubmitted	during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING - SH 6681C - TP	New	400.00	380.00
2	SPRAYPAINT - FRT FENDER LH ETC	New	600.00	560.00
		Gross Labour Cost (S\$)	1,000.00	940.00
	Report was	unsubmitted during this print-out.		

< END OF ESTIMATES >