



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2503726

16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581
ATTN: JASON TEA

INV Date 16/06/2025
Reference CD/FCI24120120/Tpa3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SJN 9944A
Insured Veh. SHC 1677E
Claim No. D24010639MFCT/CTPL/TPD-2/TJ
Policy No. D-24101861MFCT
Accident Date 03/12/2024
Inspection Date 10/12/2024

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (9%)	31.50
Grand Total	381.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN:JASON TEA			Ref: CD/FCI24120120/Tpa3q2(N) Date: 16/06/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 1677E	Veh. Inspected	SJN 9944A
	Policy No.	D-24101861MFCT	Coverage (\$)	0.00
	Claim No.	D24010639MFCT/CTPL/TPD-2/TJ	Excess (\$)	0.00
	Assign From	JASON TEA	Assign Date	10/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA SIENTA	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	NSP1707075067	Colour	WHITE
	Odometer	55204 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	CONTINENTAL	6 mm
	L/H Front Tyre	185/60 R15	CONTINENTAL	6 mm
	R/H Rear Tyre	185/60 R15	CONTINENTAL	6 mm
	L/H Rear Tyre	185/60 R15	CONTINENTAL	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	03/12/2024	Inspection Date	10/12/2024
	Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 9944A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	880.50	-
1	REAR BUMPER SIDE RETAINER LH	NOT NECESSARY	157.50	-
1	REAR BUMPER SIDE RETAINER RH	NOT NECESSARY	157.50	-
1	REAR BUMPER CENTER GARNISH	CUT	312.80	312.80
1	REAR TAILGATE	BENT	1,926.80	1,750.00
1	REAR TAILGATE LOCK	NOT NECESSARY	747.90	-
1	REAR TAILGATE WEATHERSTRIP	NOT NECESSARY	615.40	-
1	REAR TAILGATE TRIMBOARD	NOT NECESSARY	241.10	-
1	REAR TAILGATE GLASS MOULDING	NECESSARY	177.80	177.80
1	REAR END PANEL (INNER)	NOT NECESSARY	761.40	-
1	REAR END PANEL (OUTER)	TO REPAIR SEE LABOUR	1,258.90	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	252.30	-
	LESS 20% DISCOUNT		-1,497.98	-
	LESS 25% DISCOUNT		-	-560.15
			5,991.92	1,680.45
<u>SPECIAL NETT ITEMS</u>				
10	REAR BUMPER CLIPS @\$3.00 (SN)	NOT NECESSARY	30.00	-
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	35.00	-
1	WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
1	REAR REVERSE SENSOR (SN)	NOT WORKING	200.00	200.00
			325.00	260.00
<u>LABOUR</u>				
	CHECK & RECTIFY WIRING.	NOT NECESSARY	50.00	-
	REPAIR AND REPLACE AFFECTED ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR END PANEL (OUTER).		800.00	600.00
	SPRAY PAINTING (REAR BUMPER,REAR TAILGATE ,REAR END PANEL).		800.00	600.00
	REMOVE & REFIT REAR WINDSCREEN.		120.00	120.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & REPLACE REAR REVERSE SENSOR .		80.00	40.00
			1,850.00	1,360.00
GRAND TOTAL			8,166.92	3,300.45
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,600.00

Report Ref No. CD/FCI24120120/Tpa3q2(N)

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SJN 9944A



PHOTOGRAPHS FOR VEHICLE NO. : SJN 9944A





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 3 of 8)

PHOTOGRAPHS FOR VEHICLE NO. : SJN 9944A





PHOTOGRAPHS FOR VEHICLE NO. : SJN 9944A



PHOTOGRAPHS FOR VEHICLE NO. : SJN 9944A



PHOTOGRAPHS FOR VEHICLE NO. : SJN 9944A



PHOTOGRAPHS FOR VEHICLE NO. : SJN 9944A



PHOTOGRAPHS FOR VEHICLE NO. : SJN 9944A



PHOTOGRAPHS FOR VEHICLE NO. : SJN 9944A

