1/31/25, 10:44 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS24120121/EQH3M4

Date: 31/01/2025

REFERENCE

Handling Insurer: **ECICS Limited**

Policy No:

Claimant Vehicle No:

SML9437Y

Insured Vehicle No:

GBM4100B

Date of Loss:

12/10/2024

Nature of Claim:

ΤP

Claim No: DMCV2400218H/02/CT

JTDZS3EUX0J040840

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SML9437Y**

Make & Model: TOYOTA PRIUS, 1.8 PLUS (A) Reg. Date:

Grey

1798 cc

12/06/2019 (Man. Year: 2019)

Engine No: 2ZR0D52393

Odometer: 431023 km

Chassis No:

Engine Capacity: Market Value/New Car

N/A

Price:

Colour:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable):

Pre-accident Condition: No Handbrake (Serviceable): Yes Engine Modification:

CONDITION OF TYRES

205/60R16 Front Tyre Size: 205/60R16 Rear Tyre Size: Front Left Side: Rear Left Side: Toyo 5 mm Toyo 5 mm Front Right Side: Toyo 5 mm Rear Right Side: Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,049.25	2,709.00	340.25	11.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	900.00	430.00	470.00	52.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,949.25	3,139.00	810.25	20.52
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	3,949.25	2,500.00	1,449.25	36.70
+ GST 9.00/9.00% (S\$)	355.43	225.00	130.43	36.70
Nett Amount (S\$)	4,304.68	2,725.00	1,579.68	36.70

INSPECTION

Date of Assignment: 09/12/2024

MY CAR CONSULTANT PTE LTD

Date Inspected: 10/12/2024 Inspected At: 60 JALAN LAM HUAT #05-21 CARROS CENTRE

SINGAPORE 737869

Estimated Period of Repair: 2.0 days

Adjuster: **CHEN TSUE YEE** Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Yes

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 31 Jan 2025)

Parts: 144 TOYOTA PRIUS 1.8 PLUS (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SML9437Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	879.00 FL	*566.00 FL
2	1		*FRT BUMPER SIDE RETAINER LH	Not Necessary	45.00 FL	*-FL
3	1		*FRT BUMPER SIDE GARNISH LH	Cut	159.00 FL	*159.00 FL
4	1		*FRT BUMPER DAYLIGHT LH	Cut	321.00 FL	*321.00 FL
5	1		*HEADLAMP LH	Broken	2,595.00 FL	*2,526.00 FL
6	1		*SET FRT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
F=Fra	ınchise	part. S=SpcNe	ett. L=ListItemDisc.	-		
				Sub Total (S\$)	4,049.00	3,602.00
			- List Item Discount o	on L Items 25.00/25.00% (S\$)	999.75	893.00
				Total Parts (S\$)	3,049.25	2,709.00
			Report was unsubmitted	d during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	CHECK WIRING	New	100.00	30.00
2	PANEL BEAT	New	400.00	200.00
3	SPRAY PAINTING	New	400.00	200.00
		Gross Labour Cost (S\$)	900.00	430.00
		Report was unsubmitted during this print-out.		

< END OF ESTIMATES >