



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24120122/Eqh3e2
75 BRAS BASAH ROAD	Date:	27/12/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJF 6322G	Veh. Inspected	CB 7837K
Policy No.	-	Coverage	0
Claim No.	MT/1304558-001	Excess	\$0.00
Assign From	CHARLOTTE CHEW	Assign Date	10/12/2024

### 2. Vehicle Details

Make & Model	TOYOTA HIACE	C.C	2494
Engine No.	2KD1576201	Year of Reg.	02/03/2007
Chassis No.	KDH2000067946	Colour	SILVER
Odometer	967513 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: STANDARD ALLOY RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195 R15C	BRIDGESTONE	5
L/H Front Tyre	195 R15C	BRIDGESTONE	5
R/H Rear Tyre	195 R15C	BRIDGESTONE	5
L/H Rear Tyre	195 R15C	BRIDGESTONE	5

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	14/11/2024	Inspection Date	10/12/2024 (11:33)
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days