



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNA 960H

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	BROKEN	\$843.80	\$843.80
1	FRONT BUMPER LH FOGLAMP	NOT NECESSARY	\$329.00	\$0.00
2	FRONT BUMPER SIDE RETAINER L/R @\$149.10	BROKEN (1PC ONLY)	\$298.20	\$149.10
1	FRONT LH FENDER	TO REPAIR SEE LABOUR	\$1,604.50	\$0.00
1	FRONT LH FENDER INNER SHIELD	NOT NECESSARY	\$262.10	\$0.00
1	FRONT LH HEADLAMP	CUT	\$5,238.50	\$3,384.00
1	FRONT LH KNUCKLE ARM	NOT NECESSARY	\$927.80	\$0.00
1	FRONT LH KNUCKLE ARM BEARING	NOT NECESSARY	\$325.40	\$0.00
	LESS 25.00% DISCOUNT		(\$2,457.33)	(\$1,094.23)
			\$7,371.97	\$3,282.67

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	\$80.00	\$30.00
1	FRONT LH 205/55 R16 TYRE (SN)	NOT NECESSARY	\$400.00	\$0.00
1	SET FRONT LH FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	\$50.00	\$0.00
1	FRONT LH SPORT RIM (SN)	NOT NECESSARY	\$900.00	\$0.00
			\$1,430.00	\$30.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING. (TO FR)		\$80.00	\$30.00
	TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION	NOT NECESSARY	\$300.00	\$0.00
	TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL ALIGNMENTS SYSTEM		\$80.00	\$80.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT		\$900.00	\$400.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT LH FENDER		\$700.00	\$300.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL		\$100.00	\$30.00
			\$2,160.00	\$840.00
GRAND TOTAL			\$10,961.97	\$4,152.67
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$3,250.00
Report Ref No: CS/INC24120123/Evh3e2				

TOTAL FOR SPARE PARTS: \$ 8,801.97 \$ 3,312.67
TOTAL FOR LABOUR : \$ 2,160.00 \$ 840.00
TOTAL REPAIR COST: \$ 10,961.97 \$ 4,152.67

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.