



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SHB 7822T

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	COVER, FRONT BUMPER	CRACKED	\$653.31	\$653.31
1	ABSORBER, FRONT BUMPER ENERGY	SERVICEABLE	\$100.17	\$0.00
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER	TO REPAIR SEE LABOUR	\$902.16	\$0.00
1	STAY SUB-ASSY, FRONT BUMPER, LH	TO REPAIR SEE LABOUR	\$59.85	\$0.00
1	BRACKET, FRONT BUMPER SIDE, LH	DISTORTED	\$74.97	\$74.97
1	SUPPORT, RADIATOR, UPPER LH	SERVICEABLE	\$99.33	\$0.00
1	HOOD SUB-ASSY	TO REPAIR SEE LABOUR	\$1,243.20	\$0.00
1	HINGE ASSY, HOOD, LH	TO REPAIR SEE LABOUR	\$74.34	\$0.00
1	HINGE ASSY, HOOD, RH	TO REPAIR SEE LABOUR	\$74.34	\$0.00
1	LAMP ASSY, FOG, LH	SERVICEABLE	\$1,200.78	\$0.00
1	UNIT ASSY, HEADLAMP, LH	CRACKED	\$3,325.56	\$3,325.56
1	FENDER SUB-ASSY, FRONT LH	TO REPAIR SEE LABOUR	\$1,236.69	\$0.00
1	EMBLEM, SIDE PANEL LH	NECESSARY	\$68.88	\$68.88
1	LINER, FRONT FENDER, LH	SERVICEABLE	\$255.36	\$0.00
	LESS 25.00% DISCOUNT		(\$2,342.24)	(\$1,030.68)
			\$7,026.70	\$3,092.04
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRT BUMPER CLIP (SN)	NECESSARY	\$65.00	\$60.00
1	FENDER LINER CLIP (SN)	NOT NECESSARY	\$130.00	\$0.00
1	FRT LH BUMPER RETAINER CLIP (SN)	NOT NECESSARY	\$65.00	\$0.00
			\$260.00	\$60.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	NOT NECESSARY	\$380.00	\$0.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REINFORCEMENT SUB-ASSY, FRONT BUMPER, STAY SUB-ASSY, FRONT BUMPER, LH, HOOD SUB-ASSY, HINGE ASSY, HOOD, LH, HINGE ASSY, HOOD, RH AND FENDER SUB-ASSY, FRONT LH		\$1,400.00	\$300.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION		\$1,400.00	\$440.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	NOT NECESSARY	\$240.00	\$0.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED		\$170.00	\$20.00
			\$3,590.00	\$760.00
GRAND TOTAL			\$10,876.70	\$3,912.04
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$3,150.00
Report Ref No: CS/FCI24120135/Knh3e2				

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.