

ASS. REC. BY:

REF:

LPC / CS / LPC24120136 / Kmh3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

5

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Ready Auto Care Pte Ltd - We Care For All Your Car Needs

Blk 10 # 03-06 AMK Auto Point, Ang Mo Kio Ind Park 2A, Ang Mo Kio Ave 5. Singapore 568047

Tel : 64810304 Fax : 64815587

Reg No : 200600989K

GST No : 200600989K

Longpac

Motorcar Claim Department

Attn Officer In Charge

Estimate Repair

Date : 10/12/2024

Accident Involving SMG6462U & YP7369K ON 8 DEC 2021

SMG6462U

HONDA HRV

Not Authorized
Remy Bepain
84444.88

Item	Descriptions	Amount	
1	Tail Gate	\$ 1,093.50	✓
2	Tail Gate Lock	\$ 178.20	X
3	Third Brake Light	\$ 248.00	X
4	Tail Gate Center Chrome Garnish	\$ 274.20	✓
5	Tail Gate Windscreen Moulding RH & LH @\$24.80 X 2	\$ 49.60	✓
6	RL Tail Lamp	\$ 438.50	✓
7	RL Tail Gate Reflector	\$ 294.60	✓
8	RL Bumper Corner	\$ 107.30	✓
9	Rear Bumper	\$ 583.30	✓
10	RL Bumper Reflector	\$ 185.20	✓
11	RL Bumper Retainer	\$ 19.80	✓
12	Rear End Panel	\$ 498.60	X
13	RL Wheel Arch	\$ 191.60	✓
14	Rear Center Lock Buzzer	\$ 82.50	X
208			
Total For Parts		\$ 4,244.90	

S/N Item (s)

1	Rear Bumper Clips	\$ 35.00	✓
2	HRV Emblem	\$ 24.80	✓
3	HONDA Logo	\$ 24.80	✓
4	Rear Windscreen Sealant	\$ 40.00	✓
5	Rear Parking Sensor - 1 Set 4 Pcs	\$ 387.90	✓
200SN Seal			
Total For S/N		\$ 512.50	

Labour & Misc

1	To Remove All Damaged Parts, Knock Out Dents, Jack Out Damaged Panel	\$ 1,600.00	700d
2	Panel, Adjust, Replace, Reshape, Cut, Weld, Refix & Realign Body Structure	\$ 700.00	650d
3	Spray Painting For New And Repair Parts Including Supply Of Paints Materials	\$ 150.00	120d
4	Remove & Refix Rear Windscreen To Facilitate Repair	\$ 80.00	30d
5	Check Wiring, Lighting System & Center Locking For Proper Function	\$ 120.00	30d
		\$ 2,650.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Total For Parts & Labour \$ 7,407.40

No Of Days For Repair

6 Days ?
5 days

Ready Auto Care Pte Ltd

Acknowledged by Repairer

Signature:

Date: