



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNR 5296U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	TORN	3,254.00	3,254.00
1	FRONT BUMPER SIDE HOLDER	NOT NECESSARY	101.00	-
1	HEADLAMP	CRACKED	3,418.00	3,418.00
1	HEADLAMP LOWER BRACKET	CRACKED	147.00	147.00
1	HEADLAMP LOWER MOUNTING	CRACKED	98.00	98.00
1	FRONT FENDER	DENTED	1,190.00	1,190.00
1	FRONT FENDER INNER SHIELD (FRONT)	DEFORMED	303.00	303.00
1	FRONT FENDER INNER SHIELD (REAR)	NOT NECESSARY	315.00	-
1	BONNET	TO REPAIR SEE LABOUR	4,651.00	-
1	FRONT SHOCK ABSORBER	NOT NECESSARY	1,483.00	-
1	FRONT SHOCK ABSORBER FORK ARM	NOT NECESSARY	366.00	-
1	FRONT KNUCKLE ARM	NOT NECESSARY	1,136.00	-
1	FRONT WHEEL HUB	DAMAGED	479.00	479.00
1	FRONT WHEEL HUB BEARING	DAMAGED	246.00	246.00
1	FRONT UPPER ARM	NOT NECESSARY	561.00	-
1	FRONT LOWER ARM	BENT	539.00	539.00
1	FRONT CONTROL ARM	BENT	458.00	458.00
1	FRONT ANTI ROLL BAR LINKAGE	NOT NECESSARY	192.00	-
1	STEERING RACK & PINION	NOT NECESSARY	6,782.00	-
	LESS 5% DISCOUNT		-1,285.95	-506.60
			24,433.05	9,625.40
1	FRONT WHEEL RIM (SN)	CUT	1,652.00	800.00
	LESS 5% DISCOUNT		-82.60	-
			1,569.40	800.00
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	SET FRONT FENDER INNER SHIELD CLIPS (SN)	NECESSARY	30.00	30.00

Report Ref No. CS/AGI24120137/Aqh3m4(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT TYRE (SN)	NOT NECESSARY	380.00	-
			460.00	80.00
	LABOUR			
	PANEL BEATING, REMOVE AND REFIT PARTS. INCLUSIVE OF THE REPAIR OF BONNET.		800.00	500.00
	SPRAY PAINTING TO AFFECTED AREA.		800.00	600.00
	WIRING CHECK.		50.00	30.00
	TO SPRAY TUFF COAT.		100.00	30.00
	TO REMOVE FRONT UNDERCARRIAGE.		380.00	200.00
	TO REMOVE STEERING RACK & PINION.	NOT NECESSARY	180.00	-
	TO PERFORM WHEEL ALIGNMENT.		150.00	80.00
	TO PERFORM DIAGNOSTIC TEST.		200.00	150.00
			2,660.00	1,590.00
GRAND TOTAL			29,122.45	12,095.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,600.00

Report Ref No. CS/AGI24120137/Aqh3m4(N)

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.